

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20010069/DQF3Q2

Date: 05/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001250831

Claimant

Vehicle No : SH9667A

Insured Vehicle No : YQ1638T

Date of Loss: 18/09/2020

Nature of Claim: TP

Claim No: 247715

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH9667A**

Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A)

Engine No: G4LEJU032193

Reg. Date: 28/09/2018 (Man. Year: 2018)

Chassis No: KMHC851CVKU114707

Colour: Blue

Odometer: 169832 km

Engine Capacity: 1580 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: West Lake 5 mm

Rear Left Side:

West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side:

West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,044.72	11,844.80	6,199.92	34.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,590.00	2,200.00	2,390.00	52.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,634.72	14,044.80	8,589.92	37.95
+ GST 7.00/7.00% (S\$)	1,584.43	983.14	601.29	37.95
Nett Amount (S\$)	24,219.15	15,027.94	9,191.21	37.95

INSPECTION

Date of Assignment: 21/09/2020

Date Inspected: 21/09/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming

Industrial Estate

Singapore 575644

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Jan 2021)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH9667A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent/Dented	2,480.40 FL	*2,480.40 FL
2	2		*BOOT LID HINGE LH/RH	Not Necessary	142.60 FL	*- FL
3	1		*BOOT LID ABSORBER LH	Not Necessary	86.70 FL	*- FL
4	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
5	1		*EMBLEM-HYBRID	Necessary	24.30 FL	*24.30 FL
6	1		*EMBLEM-IONIQ	Necessary	31.30 FL	*31.30 FL
7	1		*BOOT LID LAMP LH	Cracked	794.40 FL	*794.40 FL
8	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
9	1		*BOOT LID TRIMBOARD SIDE LH	Not Necessary	92.50 FL	*- FL
10	1		*REAR BUMPER	Dented	459.40 FL	*459.40 FL
11	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
12	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH	Not Necessary	376.20 FL	*- FL
13	1		*ANTENNA ASSY-SMARTK	Not Necessary	689.50 FL	*- FL
14	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
15	1		*REAR BUMPER SIDE RETAINER LH	Broken	85.80 FL	*85.80 FL
16	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
17	1		*REAR BUMPER SIDE UNDER LH	Broken	123.10 FL	*123.10 FL
18	1		*REAR BUMPER REFLECTOR LAMP LH	Serviceable	82.90 FL	*- FL
19	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
20	1		*REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	Not Necessary	328.60 FL	*- FL
21	1		*LICENCE LAMP LH	Not Necessary	85.30 FL	*- FL
22	1		*LICENCE LAMP WIRE	Not Necessary	135.80 FL	*- FL
23	1		*TAIL LAMP LH	Broken	870.40 FL	*870.40 FL
24	1		*TAIL LAMP QUARTER PANEL LH	Dented	208.90 FL	*208.90 FL
25	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
26	1		*REAR PANEL GARNISH	Not Necessary	346.80 FL	*- FL
27	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
28	1		*SPARE WHEEL LOCK NUT	Not Necessary	89.50 FL	*- FL
29	1		*SPARE TYRE PANEL	Not Necessary	892.50 FL	*- FL
30	1		*REAR TRAY TOOLS BOX LH	Not Necessary	693.20 FL	*- FL
31	1		*REAR FENDER LH	Dented	1,768.30 FL	*1,768.30 FL
32	1		*REAR FENDER SHIELD REAR PIECE LH	Not Necessary	173.60 FL	*- FL
33	1		*REAR FENDER AIR-DUCT LH	Deformed	87.30 FL	*87.30 FL
34	1		*REAR FENDER TRIM BOARD LH	Not Necessary	788.75 FL	*- FL
35	1		*ASSY BSD BLIND SPOT RADAR LH	Damaged	1,625.00 FL	*1,625.00 FL
36	1		*REAR TYRE RIM LH	Dented	1,124.20 FL	*1,124.20 FL
37	1		*REAR WHEEL HUP-CAP LH	Cut	346.40 FL	*346.40 FL
38	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
39	1		*REAR TRAILING ARM LH	Distorted	265.40 FL	*265.40 FL
40	1		*REAR ASSIST LH	Distorted	227.90 FL	*227.90 FL
41	1		*REAR SHOCK ABSORBER LH	Distorted	230.50 FL	*230.50 FL
42	1		*REAR SHOCK ABSORBER MOUNTING LH	Not Necessary	133.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR ABSORBER STOPPER LH	Not Necessary	137.60 FL	*- FL
44	1		*REAR ABSORBER COVER LH	Not Necessary	175.60 FL	*- FL
45	1		*REAR CROSSMEMBER	Distorted	1,468.70 FL	*1,468.70 FL
46	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
47	1		*STABILIZER LINK LH	Not Necessary	147.30 FL	*- FL
48	1		*REAR UPPER ARM LH	Distorted	239.50 FL	*239.50 FL
49	1		*REAR LOWER ARM LH	Distorted	393.10 FL	*393.10 FL
50	1		*REAR KNUCKLE ARM LH	Distorted	538.10 FL	*538.10 FL
51	1		*REAR BUMPER CENTRE LOWER GRILLE	Mounting Broken	451.25 FL	*47.50 FL
52	1		*REAR BUMPER UNDER CENTRE	Mounting Broken	123.85 FL	*123.85 FL
53	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	35.00 FS	*35.00 FS
54	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
55	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
56	1		*REAR TYRE LH	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	22,435.65	14,784.75
- List Item Discount on L Items 20.00/20.00% (S\$)	4,390.93	2,939.95
Total Parts (S\$)	18,044.72	11,844.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	900.00
2	SPRAY PAINTING CHARGE	New	1,200.00	800.00
3	WIRING CHARGE	New	160.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
7	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
8	RE-SET REAR ABS SYSTEM	New	400.00	0.00
9	FOUR WHEEL ALIGNMENT	New	120.00	60.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	180.00
Gross Labour Cost (\$\$)			4,590.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >