

ASSIGNMENT

COE Sept 2026

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1001750831Claims No. 247715

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
☒	☐

Bal. or Market Value: _____

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 71P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SH 9667A Yr Regn: 2018 / Sept

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 169832 T/Radio: Insured / Std / NI / NAEng/No: G4LEJU032193C/No: KMHCB51CVKU114707

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 18/09/2020 D.O.A. 21/09/2020Survey held at Bijrost Sim Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MSG YQ 1638T

1/10 Sent Preli by Momen

28/12/2020 Jmcr 71P 14,044.80 at 8 days 8 days 8 days
(ded # 8589.92, 2451.0)

Date/Time, File Pass to?

1/20/12 Jmcr

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 8Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S+RS, SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: MEM-TPLump Sum / I.B.f. (\$) (14044.80)

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 18-Sep-20

INSURANCE: MSIG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH 9667 A

Description	Qty	List Price	Amount	
Boot Lid <i>dent</i>	1	\$ 2,480.40	\$ 2,480.40	✓
Boot Lid Hinge (LH/RH) <i>NH</i>	2	\$ 71.30	\$ 142.60	X
Boot Lid Absorber (LH) <i>NH</i>	1	\$ 86.70	\$ 86.70	X
Boot Lid 'H' Emblem <i>Hec</i>	1	\$ 28.00	\$ 28.00	✓
Emblem-Hybrid <i>Hec</i>	1	\$ 24.30	\$ 24.30	✓
Emblem-Ioniq <i>Hec</i>	1	\$ 31.30	\$ 31.30	✓
Boot Lid Lamp(LH) <i>crack</i>	1	\$ 794.40	\$ 794.40	✓
Boot Lid Trimboard Clips (10pcs) <i>NH</i>	1	\$ 11.00	\$ 11.00	X
Boot Lid Trimboard SIDE (LH) <i>NH</i>	1	\$ 92.50	\$ 92.50	X
Rear Bumper <i>Dent</i>	1	\$ 459.40	\$ 459.40	✓
Rear Bumper Reinforcement <i>NH</i>	1	\$ 394.80	\$ 394.80	X
Rear Bumper Reinforcement Bracket (LH/RH) <i>NH</i>	2	\$ 188.10	\$ 376.20	X
Antenna Assy-SMARTK <i>NH</i>	1	\$ 689.50	\$ 689.50	X
Rear Bumper Stay <i>NH</i>	1	\$ 138.10	\$ 138.10	X
Rear Bumper Side retainer (LH) <i>broken</i>	1	\$ 85.80	\$ 85.80	✓
Rear Bumper Cover Clips <i>Hec</i>	1	\$ 22.00	\$ 22.00	✓
Rear Bumper Side Under(LH) <i>broken</i>	1	\$ 123.10	\$ 123.10	✓
Rear Bumper Reflector Lamp(LH) <i>s/c</i>	1	\$ 82.90	\$ 82.90	X
Rear Bumper Towing Cover <i>NH</i>	1	\$ 98.80	\$ 98.80	X
Rear Bumper Reserve Light (Parking Brake Light) <i>NH</i>	1	\$ 328.60	\$ 328.60	X
Licence Lamp (LH) <i>NH</i>	1	\$ 85.30	\$ 85.30	X
Licence Lamp WIRE <i>NH</i>	1	\$ 135.80	\$ 135.80	X
Tail Lamp(LH) <i>broken</i>	1	\$ 870.40	\$ 870.40	✓
Tail Lamp Quarter Panel(LH) <i>Dent</i>	1	\$ 208.90	\$ 208.90	✓
Rear Panel <i>Dent</i>	1	\$ 532.00	\$ 532.00	✓
Rear Panel Garnish <i>NH</i>	1	\$ 346.80	\$ 346.80	X
Spare Tyre Holder <i>NH</i>	1	\$ 223.10	\$ 223.10	X
Spare Wheel Lock Nut <i>NH</i>	1	\$ 89.50	\$ 89.50	X
Spare Tyre Panel <i>NH</i>	1	\$ 892.50	\$ 892.50	X
Rear tray tools box LH <i>NH</i>	1	\$ 693.20	\$ 693.20	X
Rear Fender(LH) <i>Dent</i>	1	\$ 1,768.30	\$ 1,768.30	✓
Rear Fender SHIELD REAR PIECE (LH) <i>NH</i>	1	\$ 173.60	\$ 173.60	X
Rear Fender Air-Duct (LH) <i>side deformed</i>	1	\$ 87.30	\$ 87.30	X ✓
Rear Fender Trim Board (LH) <i>NH</i>	1	\$ 788.75	\$ 788.75	X
Assy BSD Blind Spot Radar (LH) <i>Dent</i>	1	\$ 1,625.00	\$ 1,625.00	✓
Rear Tyre Rim (LH) <i>NH Dent</i>	1	\$ 1,124.20	\$ 1,124.20	X ✓
Rear Wheel Hup-Cap (LH) <i>NH out</i>	1	\$ 346.40	\$ 346.40	X ✓
Rear Wheelbearing & Hub assy <i>to Dent</i>	1	\$ 554.00	\$ 554.00	✓
Rear Trailing Arm(LH) <i>2 deformed</i>	1	\$ 265.40	\$ 265.40	✓
Rear Assist (LH) <i>2 deformed</i>	1	\$ 227.90	\$ 227.90	✓
Rear shock Absorber(LH) <i>2 deformed</i>	1	\$ 230.50	\$ 230.50	✓
Rear Shock Absorber Mounting (LH) <i>NH</i>	1	\$ 133.10	\$ 133.10	X

Rear Absorber stopper (LH) NH	1	\$ 137.60	\$ 137.60	X
Rear Absorber Cover (LH) NH	1	\$ 175.60	\$ 175.60	X
Rear Crossmember NH distal	1	\$ 1,468.70	\$ 1,468.70	X ✓
Stabilizer Bar NH	1	\$ 387.30	\$ 387.30	X
Stabilizer Link (LH) NH	1	\$ 147.30	\$ 147.30	X
Rear Upper Arm(LH) 2 distal	1	\$ 239.50	\$ 239.50	2 ✓
Rear Lower Arm(LH) 2 distal	1	\$ 393.10	\$ 393.10	2 ✓
Rear Knuckle Arm (LH) 2 distal	1	\$ 538.10	\$ 538.10	2 ✓
14528.40 SUB TOTAL			\$ 21,379.55	
LESS 20%			\$ 4,275.91	
11622.72 DISCOUNTED TOTAL			\$ 17,103.64	
Boot Lid Comfort Logo & Tel No. Sticker Hec SN	1	\$ 35.00	\$ 35.00	✓
Rear Bumper Rubber Mat Hec SN	1	\$ 50.00	\$ 50.00	✓
Rear Bumper Reverse Sensor NH SN	1	\$ 180.00	\$ 180.00	X
Rear Tyre(LH) NH SN	1	\$ 216.00	\$ 216.00	X
85.00 SUB TOTAL			\$ 481.00	
Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	900/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	800/-
Wiring Charge	1	\$160.00	\$160.00	30/-
Tuff Kote	1	\$160.00	\$160.00	40/-
Towing Charge	1	\$80.00	\$80.00	NH
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00	40/-
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00	2 1/2 150/-
Re-set Rear ABS System	1	\$400.00	\$400.00	NH
Four Wheel Alignment 2200.00	1	\$120.00	\$120.00	60/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	180/-
TOTAL LABOUR			\$4,590.00	
ESTIMATE TOTAL			\$ 22,174.64	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

21/09/2020 @ 1700hrs

N/A Actual

13907.72

Part by P.A. supp 137-08

8 dgs. PIP 14,044.80

2KK Auto

Photo after repair with damaged parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 26 Dec-20

INSURANCE: MSIG.

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH 9667 A (S)

Description	Qty	List Price	Amount
Rear Bumper Centre Lower grille <i>monly broken</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Under Centre <i>monly broken</i>	1	\$ 123.85	\$ 123.85
SUB TOTAL			\$ 575.10
LESS 20%			\$ 115.02
DISCOUNTED TOTAL			\$ 460.08

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

171.35

137.08

47.50
✓