

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010085/KES3Q2

Date: 24/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900001657

Claimant

Vehicle No : SKA783M

Insured Vehicle No : SMH292C

Date of Loss: 16/09/2020

Nature of Claim: TP

Claim No: 3873658406SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA783M**

Make & Model: MITSUBISHI LANCER, 1.5 MIVEC A/T
ELEGANCE 2WD 4DR (A)

Engine No: 4A91AA8676

Reg. Date: 19/01/2011 (Man. Year: 2010)

Chassis No: JMYSRCY2ABU000409

Colour: Metallic Silver

Odometer: 202080 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Pirelli 7 mm

Rear Left Side: Pirelli 7 mm

Front Right Side: Pirelli 7 mm

Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,007.50	733.50	274.00	27.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	400.00	800.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,207.50	1,133.50	1,074.00	48.65
Approved Total (Overridden) (S\$)		900.00		
(S\$)	2,207.50	900.00	1,307.50	59.23
+ GST 7.00/7.00% (S\$)	154.53	63.00	91.53	59.23
Nett Amount (S\$)	2,362.03	963.00	1,399.03	59.23
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,090.45		

INSPECTION

Date of Assignment: 21/09/2020

Date Inspected: 22/09/2020 Inspected At:

Wei Lee Motor Works (HQ)
BLOCK 9 SIN MING INDUSTRIAL
ESTATE #01-32
Singapore 575644

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	815.00 FL	*815.00 FL
2	1		*REAR BUMPER REFLECTOR	Serviceable	20.00 FL	* - FL
3	2		*REAR BUMPER LOWER BRACKET	Serviceable	40.00 FL	* - FL
4	1		*REVERSE SENSOR	Serviceable	220.00 FS	* - FS
					Sub Total (S\$)	1,095.00 815.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	87.50 81.50
					Total Parts (S\$)	1,007.50 733.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS REPAIR /RESHAPE END PANEL,DAMAGED AREAS REPLACE /ALIGN REAR BUMPER INTO POSITION	New	700.00	200.00
2	TO SPRAY PAINT	New	500.00	200.00
Gross Labour Cost (\$\$)			1,200.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >