

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010105/ASF3Q2

Date: 19/02/2021

REFERENCE

| | | | |
|-------------------|--------------------|------------------|--------------|
| Insured/Claimant: | TAN QINGCHENG RYAN | Policy No: | 1900166839 |
| Date of Loss: | 18/09/2020 | Nature of Claim: | OD |
| | | Claim No: | 2480954576SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SMQ885U | Engine No: | CVK086892 |
| Make & Model: | AUDI A4, 2.0 (A) | Chassis No: | WAUZZZF47KA110579 |
| Reg. Date: | 25/09/2019 (Man. Year: 2019) | Odometer: | 6123 km |
| Colour: | Red | | |
| Engine Capacity: | 1984 cc | | |
| Market Value/New Car Price: | S\$132,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 245/40R18 | Rear Tyre Size: | 245/40R18 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 26,343.68 | 15,777.60 | 10,566.08 | 40.11 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,884.00 | 4,704.00 | 3,180.00 | 40.33 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 34,227.68 | 20,481.60 | 13,746.08 | 40.16 |
| - Excess (S\$) | 550.00 | 550.00 | 0.00 | 0.00 |
| (S\$) | 33,677.68 | 19,931.60 | 13,746.08 | 40.82 |
| + GST 7.00/7.00% (S\$) | 2,357.44 | 1,395.21 | 962.23 | 40.82 |
| Nett Amount (S\$) | 36,035.12 | 21,326.81 | 14,708.31 | 40.82 |

INSPECTION

| | | |
|-----------------------------|------------|----------------------------------|
| Date of Assignment: | 21/09/2020 | |
| Date Inspected: | 21/09/2020 | Inspected At: |
| | | Premium Automobiles Pte Ltd (HQ) |
| | | 55 UBI ROAD 1 |
| | | Singapore 408699 |
| Estimated Period of Repair: | 6.0 days | |

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Distorted | 2,171.00 FS | *1,736.80 FS |
| 2 | 1 | | *FRONT BUMPER FIXING PARTS | Not Necessary | 580.00 FS | *- FS |
| 3 | 2 | | *FRONT BUMPER SECURING STRIP | Damaged | 70.00 FS | *55.68 FS |
| 4 | 1 | | *FRONT BUMPER GRILLE-CENTRE | Not Necessary | 194.00 FS | *- FS |
| 5 | 1 | | *FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE | Not Necessary | 208.00 FS | *- FS |
| 6 | 1 | | *FRONT BUMPER AIR GUIDE-RH | Missing | 62.00 FS | *49.52 FS |
| 7 | 1 | | *RADIATOR GRILLE | Cracked | 2,160.00 FS | *1,728.00 FS |
| 8 | 1 | | *FRONT BUMPER AIR GUIDE GRILLE-RH | Missing | 361.00 FS | *288.80 FS |
| 9 | 1 | | *FRONT BUMPER CARRIER | Not Necessary | 795.00 FS | *- FS |
| 10 | 1 | | *FRONT BUMPER FOAM FILLER PIECE | Not Necessary | 123.00 FS | *- FS |
| 11 | 1 | | *FRONT BUMPER GUIDE SECTION-RH | Damaged | 37.00 FS | *29.52 FS |
| 12 | 1 | | *FRONT BUMPER TOP COVER | Cracked | 126.00 FS | *100.40 FS |
| 13 | 1 | | *CAUTION SIGN STICKER | Necessary | 14.00 FS | *10.80 FS |
| 14 | 1 | | *AIRCON STICKER | Necessary | 8.00 FS | *5.68 FS |
| 15 | 1 | | *LOCK CARRIER BRACKET | Cracked | 136.00 FS | *108.40 FS |
| 16 | 1 | | *FRONT BUMPER SUPPORT-LH/RH | O/s Damaged | 56.00 FS | *22.24 FS |
| 17 | 1 | | *FRONT PARKING AID SENSOR-INNER/OUTER (2 Pcs) | Outer Missing | 386.08 FS | *193.04 FS |
| 18 | 1 | | *FRONT FENDER-RH | Distorted | 758.00 FS | *606.00 FS |
| 19 | 1 | | *FRONT FENDER ATTACHMENT PARTS | Not Necessary | 200.00 FS | *- FS |
| 20 | 1 | | *FRONT FENDER CLOSING ELEMENT-RH | Bent | 49.00 FS | *39.20 FS |
| 21 | 1 | | *FRONT FENDER BRACKET-RH | Bent | 35.00 FS | *27.60 FS |
| 22 | 1 | | *DEFORMATION ELEMENT BRACKET-RH | Damaged | 49.00 FS | *38.80 FS |
| 23 | 1 | | *FRONT FENDER BRACKET | Bent | 31.00 FS | *24.80 FS |
| 24 | 1 | | *FRONT FENDER BRACKET | Bent | 33.00 FS | *26.32 FS |
| 25 | 1 | | *FRONT FENDER BRACE-RH | Bent | 117.00 FS | *93.60 FS |
| 26 | 1 | | *FRONT FENDER CLOSING ELEMENT-RH | Not Necessary | 33.00 FS | *- FS |
| 27 | 1 | | *FRONT FENDER COVER-RH | Deformed | 12.00 FS | *9.04 FS |
| 28 | 1 | | *WHEEL HOUSING LINER-RH | Deformed | 239.00 FS | *190.80 FS |
| 29 | 1 | | *WHEEL HOUSING LINER ATTACHMENT PARTS | Not Necessary | 230.00 FS | *- FS |
| 30 | 1 | | *WHEEL SPOILER-RH | Not Necessary | 73.00 FS | *- FS |
| 31 | 1 | | *WHEEL SPOILER TRIM-RH | Not Necessary | 36.00 FS | *- FS |
| 32 | 1 | | *STONE CHIP GUARD-RH | Necessary | 50.00 FS | *39.92 FS |
| 33 | 1 | | *BONNET | Dented | 2,763.00 FS | *2,210.40 FS |
| 34 | 1 | | *BONNET ATTACHMENT PARTS | Not Necessary | 408.00 FS | *- FS |
| 35 | 2 | | *BONNET LID HINGE-LH/RH | Bent | 602.00 FS | *481.60 FS |
| 36 | 1 | | *BONNET IMPACT PROTECTION-CENTRE | Necessary | 27.00 FS | *21.52 FS |
| 37 | 1 | | *BONNET IMPACT PROTECTION-LH | Necessary | 28.00 FS | *21.84 FS |
| 38 | 1 | | *BONNET IMPACT PROTECTION-RH | Necessary | 27.00 FS | *21.52 FS |
| 39 | 1 | | *TOP FENDER INNER COVER-RH | Deformed | 61.00 FS | *48.24 FS |
| 40 | 1 | | *TOP FENDER LEDGE COVER-UPPER RH | Deformed | 31.00 FS | *24.40 FS |
| 41 | 1 | | *TOP FENDER LEDGE COVER-LOWER RH | Deformed | 23.00 FS | *17.68 FS |
| 42 | 1 | | *BONNET GAS FILLED STRUT | Damaged | 118.00 FS | *94.00 FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|---------------------------|----------------------------|
| 43 | 2 | | *BONNET STRIKER-LH/RH | Bent | 100.00 FS | *78.88 FS |
| 44 | 1 | | *BONNET LID LOCK | Not Necessary | 212.00 FS | *- FS |
| 45 | 1 | | *PLENUM CHAMBER COVER | Cut | 96.00 FS | *76.64 FS |
| 46 | 1 | | *BONNET SOUND ABSORBER | Not Necessary | 339.00 FS | *- FS |
| 47 | 1 | | *LED HEADLIGHT-RH | Cracked | 7,693.00 FS | *6,154.40 FS |
| 48 | 1 | | *MAIN LIGHT ELECTRONICS POWER MODULE | Not Necessary | 739.00 FS | *- FS |
| 49 | 1 | | *LIGHT CONTROL SYSTEM CONTROL UNIT | Not Necessary | 742.00 FS | *- FS |
| 50 | 1 | | *HEADLAMP REPAIR KIT-RH | Not Necessary | 130.00 FS | *- FS |
| 51 | 1 | | *HEADLIGHT HOSE-RH | Not Necessary | 36.00 FS | *- FS |
| 52 | 1 | | *HEADLIGHT COMPENSATING PIECE | Not Necessary | 40.00 FS | *- FS |
| 53 | 1 | | *HEADLIGHT COMPENSATING PIECE | Not Necessary | 40.00 FS | *- FS |
| 54 | 1 | | *HEADLIGHT COMPENSATING PIECE | Not Necessary | 40.00 FS | *- FS |
| 55 | 1 | | *LIFT CYLINDER-RH | Not Necessary | 208.00 FS | *- FS |
| 56 | 1 | | *LIFT CYLINDER CORRUGATED PIPE | Not Necessary | 92.00 FS | *- FS |
| 57 | 1 | | *LIFT CYLINDER CORRUGATED PIPE | Not Necessary | 38.00 FS | *- FS |
| 58 | 1 | | *HEADLIGHT WASHER PUMP | Not Necessary | 151.00 FS | *- FS |
| 59 | 1 | | *WASH WATER RESERVOIR | Cracked | 146.00 FS | *116.40 FS |
| 60 | 1 | | *WINDSCREEN WASHER SYSTEM PUMP | Not Necessary | 121.00 FS | *- FS |
| 61 | 1 | | *WINDOW SLOT SEAL-RH | Not Necessary | 303.00 FS | *- FS |
| 62 | 1 | | *WINDOW GUIDE TRIM STRIP | Not Necessary | 254.00 FS | *- FS |
| 63 | 1 | | *FRONT ALUMINIUM RIM-RH | Cut | 80.00 FS | *80.00 FS |
| 64 | 1 | | *FRONT TYRE-RH | Cut | 410.00 FS | *410.00 FS |
| 65 | 1 | | *SUNDRIES | Necessary | 350.00 FS | *31.52 FS |
| 66 | 1 | | *FRONT NUMBER PLATE | Necessary | 60.00 FS | *60.00 FS |
| 67 | 1 | | *FRONT BUMPER WIRING SET | Snapped | 403.60 FS | *403.60 FS |
| | | | | | Total Parts (\$\$) | 26,343.68 15,777.60 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID | New | 480.00 | 480.00 |
| 2 | TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE | New | 350.00 | 250.00 |
| 3 | TO DISMANTLE RHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL RHS WING MIRROR ASSY | New | 350.00 | 0.00 |
| 4 | TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,BONNET AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | New | 2,800.00 | 1,500.00 |
| 5 | TO RESPRAY FRONT BUMPER,RHS FRONT FENDER,BONNET,BONNET HINGES AND RHS FRONT DOOR | New | 3,000.00 | 1,810.00 |
| 6 | TO RENEW RHS FRONT RIM WITH TYRE.TO CARRY OUT PRE AND POST WHEEL ALIGNMENT TEST | New | 520.00 | 280.00 |
| 7 | TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK | New | 384.00 | 384.00 |
| Gross Labour Cost (\$\$) | | | 7,884.00 | 4,704.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >