



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SKX4822LMake & Model : TOYOTA ALTISYear of Manufacture : 2015Chassis No. : MR053REH104543958Engine No. : 1ZRY246199

Policy No. : _____

Time of Accident : 07.30Ins Company : MS FIRST CAPITAL

Excess : _____

Date of Accident : 16/09/2020

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : _____

Signature : _____

Contact No

68485725/26 - JOHARI/TINIE

Parts (a) Cost / List Price Items \$ 12,396.30Plus/Less 25% \$ 3,099.08Total of Cost / List \$ 9,297.22(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 9,297.22Labour (Appendix B) \$ 2,630.00Total Repair Cost \$ 11,927.22

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Adrian KingCompany : LKICSurvey conducted on : 22/09/20 at 13:45 hr.Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ 888(e) Signature of surveyor : [Signature] Date: 22/09/20

Lump Sum Repairs

Spark Car Care

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649

TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SKX4822L Case Owner : _____

Make & Model : TOYOTA ALTIS Year Manufacture : 2015

Chassis No : MR053REH104543958 Engine No : 1ZRY246199

HV : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	BONNET <i>Dented</i>	1		\$ 1,685.88	✓ 1190.40		
2	BONNET HINGE RH <i>2</i>	1		\$ 79.51	+		
3	BONNET HINGELH <i>3</i>	1		\$ 79.51	+		
4	BONNET RUBBER <i>3</i>	1		\$ 43.20	+		
5	BONNET LOCK <i>3</i>	1		\$ 182.25	+		
6	LHF HEADLAMP <i>Cracked</i>	1		\$ 3,602.50	2568		
7	LHF FENDER <i>Distorted</i>	1		\$ 1,226.74	790.40		
8	LHF FENDER COWLING <i>Distorted</i>	1		\$ 282.28	✓		
9	LHF FENDER COWLING CLIP'S <i>3</i>	8		\$ 24.88	✓		
10	LHF FENDER DUAL VVT-I <i>New</i>	1		\$ 47.92	✓		
11	RADIATOR GRILLE ASSY <i>New</i>	1		\$ 868.05	+		
12	RADIATOR SUPPORT PANEL <i>3</i>	1		\$ 1,534.00	+		
13	FRONT BUMPER <i>Distorted</i>	1		\$ 716.88	589.70		
14	FRONT BUMPER CLIP'S <i>New</i>	15		\$ 91.05	30		
15	FRONT BUMPER SIDE RETAINER LH <i>Distorted</i>	1		\$ 115.42	55.90		
16	FRONT BUMPER SPONGE <i>3</i>	1		\$ 121.63	+		
17	FRONT BUMPER REINFORCEMENT <i>3</i>	1		\$ 539.32	+		
18	FOG LAMP LH <i>3</i>	1		\$ 419.04	+		
19	FOR LAMP COVER LH <i>3</i>	1		\$ 152.14	+		
20	RESONATOR TANK <i>Cracked</i>	1		\$ 144.45	2		
21	RESONATOR TANK TUBE UPPER <i>New</i>	1		\$ 181.03	+		
22	RESONATOR TANK TUBE LOWER <i>Distorted</i>	1		\$ 258.52	2		
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

5932.45
len 25%: 4449.33

Spark Car Care

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649

Tel: 68438723/68438736 FAX : 67436072

Labour

Vehicle No. : SKX4822L Case Owner : JOHARI
Make & Model : TOYOTA ALTIS Year of Manufacture : 2015

S/No	Labour Description	Estimated Price	Adjusted Price
	To disconnect and check electrical wiring , wire sockets ,etc , remove	\$100.00	30
	reinstall damage parts , test and retify for proper functioning .		
	TO CUT AND WELD RADIATOR SUPPORT PANEL , KNOCK & REPAIR LHF	\$1,050.00	600
	FENDER INNER PANEL , LHF WHEEL HOUSE , LHF DOOR AND		
	AFFECTED AREA		
	TO PUTTY & SPRAY PAINT FRT BONNET , FRT BUMPER , FRT FENDER ,INNER	\$1,200.00	800
	PANEL , WHEEL HOUSE , LHF DOOR AND AFFECTED AREA		
	REPROGRAM HEADLAMP	\$280.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1430

Supplementary: 2064

total: 7943.33

L/s: 6350 :
05 Days.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 Fax:67436072

Supplementary 1

Vehicle No : SKX4822L Case Owner : _____
Make & Model : TOYOTA ALTIS 1.6L Year Manufact : 2015
Chassis No : _____ Engine No : _____
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	HEADLAMP CHROME MOULDING LH <i>ut</i>	1		\$ 250.00	<i>✓</i>	<i>184.</i>	
2	HEADLAMP RH <i>Cracked</i>	1		\$3,602.50	<i>✓</i>		
3					<i>2568.</i>		
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62844284,62815767

Resenged
Admin
29/09/20.
HL