



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : SKX4822LMake & Model : TOYOTA ALTISYear of Manufacture : 2015Chassis No. : MR053REH104543958Ins Company : MS FIRST CAPITALEngine No. : 1ZRY246199

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 16/09/2020Time of Accident : 07.30

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimates**

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Contact No : \_\_\_\_\_

**Parts (a) Cost / List Price Items** \$ 12,396.30Plus/Less 25% \$ 3,099.08Total of Cost / List \$ 9,297.22(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -**Total Parts Cost (Appendix A)** \$ 9,297.22**Labour (Appendix B)** \$ 2,630.00**Total Repair Cost** \$ 11,927.22

68485725/26 - JOHARI/TINIE

*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : \_\_\_\_\_

Company : \_\_\_\_\_

Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
320 UBI ROAD 3 SINGAPORE 408649  
TEL :68438723/68438736 Fax:67436072

## Spare Parts

Vehicle No : **SKX4822L** Case Owner : \_\_\_\_\_

Make & Model : **TOYOTA ALTIS** Year Manufacture : **2015**

Chassis No : **MR053REH104543958** Engine No : **1ZRY246199**

HV : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : **TP**

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	BONNET	1		\$ 1,685.88			
2	BONNET HINGE RH	1		\$ 79.51			
3	BONNET HINGELH	1		\$ 79.51			
4	BONNET RUBBER	1		\$ 43.20			
5	BONNET LOCK	1		\$ 182.25			
6	LHF HEADLAMP	1		\$ 3,602.50			
7	LHF FENDER	1		\$ 1,226.74			
8	LHF FENDER COWLING	1		\$ 282.28			
9	LHF FENDER COWLING CLIP'S	8		\$ 24.88			
10	LHF FENDER DUAL VVT-I	1		\$ 47.92			
11	RADIATOR GRILLE ASSY	1		\$ 868.05			
12	RADIATOR SUPPORT PANEL	1		\$ 1,534.00			
13	FRONT BUMPER	1		\$ 716.98			
14	FRONT BUMPER CLIP'S	15		\$ 91.05			
15	FRONT BUMPER SIDE RETAINER LH	1		\$ 115.42			
16	FRONT BUMPER SPONGE	1		\$ 121.63			
17	FRONT BUMPER REINFORCEMENT	1		\$ 539.32			
18	FOG LAMP LH	1		\$ 419.04			
19	FOR LAMP COVER LH	1		\$ 152.14			
20	RESONATOR TANK	1		\$ 144.45			
21	RESONATOR TANK TUBE UPPER	1		\$ 181.03			
22	RESONATOR TANK TUBE LOWER	1		\$ 258.52			
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

## Spark Car Care

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649

Tel: 68438723/68438736 FAX : 67436072

### Labour

Vehicle No. : SKX4822L Case Owner : JOHARI  
Make & Model : TOYOTA ALTIS Year of Manufacture : 2015

S/No	Labour Description	Esimated Price	Adjusted Price
	To disconnect and check electrical wiring , wire sockets ,etc , remove	\$100.00	
	reinstall damage parts , test and retify for proper functioning .		
	TO CUT AND WELD RADIATOR SUPPORT PANEL , KNOCK & REPAIR LHF	\$1,050.00	
	FENDER INNER PANEL , LHF WHEEL HOUSE , LHF DOOR AND		
	AFFECTED AREA		
	TO PUTTY & SPRAY PAINT FRT BONNET , FRT BUMPER , FRT FENDER ,INNER	\$1,200.00	
	PANEL , WHEEL HOUSE , LHF DOOR AND AFFECTED AREA		
	REPROGRAM HEADLAMP	\$280.00	

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*