

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010112/T1GA3Q2
Date: 16/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100391249
Claimant Vehicle No :	SHD3072G	Insured Vehicle No :	SKQ1317K
Date of Loss:	20/09/2020	Nature of Claim:	TP
		Claim No:	0770431433SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3072G	Engine No:	D4FDGU651412
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU091446
Reg. Date:	16/06/2016 (Man. Year: 2016)	Odometer:	314665 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,575.36	1,952.16	623.20	24.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,110.00	880.00	230.00	20.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,685.36	2,832.16	853.20	23.15
Approved Total (Overridden) (S\$)		2,250.00		

Adjuster Report				
(S\$)	3,685.36	2,250.00	1,435.36	38.95
+ GST 7.00/7.00% (S\$)	257.98	157.50	100.48	38.95
Nett Amount (S\$)	3,943.34	2,407.50	1,535.84	38.95
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment:	21/09/2020		
Date Inspected:	21/09/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster:	MOHD TAUFIKH BIN HAMID	Manager:	Chong Pui Lin
-----------	------------------------	----------	---------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cut	1,388.00 FL	*1,388.00 FL
2	1		*FRONT BUMPER SIDE BRACKET LH	Not Necessary	22.40 FL	*- FL
3	1		*FRT FENDER LH	Repair	663.00 FL	*- FL
4	1		*FRONT BUMPER ASSY	Deformed	1,052.20 FL	*1,052.20 FL
5	1		*FRT BUMPER GRILLE LH	Not Necessary	93.60 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	3,219.202,440.20
					- List Item Discount on L Items 20.00/20.00% (\$)	643.84488.04
					Total Parts (\$)	2,575.361,952.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	540.00	420.00
2	SPRAY PAINTING CHARGE	New	450.00	400.00
3	CHECK WIRING	New	60.00	30.00
4	TUFF KOTE	New	60.00	30.00
Gross Labour Cost (\$\$)			1,110.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >