

REPAIR ESTIMATE*

VEHICLE NO SHD3072G

MAKE :

MODEL HYU- I40

DATE 01/09/20 12:00 AM

CHIANG / N 719

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	HEADLAMP LH			\$1,388.00
1	FRONT BUMPER SIDE BRACKET LH			\$22.40
1	FRT FENDER LH			\$663.00
1	FRONT BUMPER ASSY			\$1,052.20
1	FRT BUMPER GRILLE LH			\$93.60
	SUB TOTAL		2440.20.	\$3,219.20
	20.00%			\$643.84
	DISCOUNTED TOTAL		1952.16.	\$2,575.36
				\$-
	Labour Charge			
	Panel Beating			\$540.00
	Spray Painting Charge			\$450.00
	Check wiring			\$60.00
	Tuff kote			\$60.00
	TOTAL LABOUR		880.	\$1,110.00
	ESTIMATE TOTAL		2832.16	\$3,685.36
			1/5 \$2250	
			.3 days	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphih 97445744
 WP' 21/9/20 CS
 C/S Resurvey after repair
 for Phih 2-3 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: