

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 1616M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	2,480.00	-
1	FRONT DOOR INNER RUBBER O/S	NOT NECESSARY	315.00	-
1	REAR DOOR O/S	BADLY DENTED	2,380.00	1,203.80
1	REAR DOOR INNER RUBBER O/S	NECESSARY	315.00	171.90
1	REAR DOOR FRAME STICKER O/S	NECESSARY	285.00	185.00
	LESS 5% DISCOUNT		-	-78.04
			5,775.00	1,482.66
	<u>LABOUR</u>			
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO RESET & REPROGRAMME SYSTEM.		150.00	80.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	TO TRANSFER REAR DOOR MECHANISM.		100.00	60.00
	TO SPRAY CERAMIC COATING.		450.00	200.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR O/S.		580.00	380.00
	TO PUTTY & SPRAY PAINTING.		680.00	400.00
			2,090.00	1,150.00
	GRAND TOTAL		7,865.00	2,632.66
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CS/SMO20010118/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.