

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010120/UVF3E2

Date: 07/10/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNA00001431900	
Claimant Vehicle No : SJL408B	Insured Vehicle No : GBK587S	
Date of Loss: 18/09/2020	Nature of Claim: TP	Claim No: SNM20D203424C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL408B		
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)	Engine No:	4A910109801
Reg. Date:	13/11/2008 (Man. Year: 2008)	Chassis No:	JMYSRCY2A9U000527
Colour:	Red	Odometer:	161129 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,575.60	5,282.50	25,293.10	82.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,170.00	2,220.00	8,950.00	80.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,745.60	7,502.50	34,243.10	82.03
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	41,745.60	6,000.00	35,745.60	85.63
+ GST 7.00/7.00% (S\$)	2,922.19	420.00	2,502.19	85.63
Nett Amount (S\$)	44,667.79	6,420.00	38,247.79	85.63

INSPECTION

Date of Assignment:	21/09/2020	
Date Inspected:	22/09/2020 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2020)
Parts:	143	mitsubishi LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL408B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	377.00 FL	*- FL
2	1		*BOOT LID	Badly Dented	1,341.00 FL	*885.00 FL
3	1		*BOOTLID THIRD BRAKE LAMP	Not Necessary	352.00 FL	*- FL
4	1		*BOOT LID LOGO (MITSUBISHI)	Necessary	105.00 FL	*42.00 FL
5	1		*BOOTLID EMBLEM (LANCER)	Necessary	112.00 FL	*45.00 FL
6	1		*BOOTLID EMBLEM (EX)	Necessary	95.00 FL	*38.00 FL
7	1		*BOOTLID EMBLEM (C&C)	Necessary	107.00 FL	*45.00 FL
8	1		*BOOT LID LAMP (L+R)	N/S Cracked	1,486.00 FL	*188.00 FL
9	1		*BOOT LID LOCK	Twisted	359.00 FL	*109.00 FL
10	1		*BOOT LID LOCK CATCH	Not Necessary	96.00 FL	*- FL
11	1		*BOOT LID INNER TRIM	Deformed / Tron	512.00 FL	*245.00 FL
12	2		*BOOT LID HINGE (L+R)	Not Necessary	424.00 FL	*- FL
13	2		*BOOT LID DAMPER (L+R)	Not Necessary	652.00 FL	*- FL
14	2		*BOOT LID STOPPER (L+R)	Not Necessary	46.00 FL	*- FL
15	1		*BOOT LID WEATHER STRIP	Twisted	375.00 FL	*185.00 FL
16	2		*TAIL LAMP (L+R)	Cracked	1,794.00 FL	*850.00 FL
17	2		*TAIL LAMP PANEL (L+R)	Repair	850.00 FL	*- FL
18	1		*REAR BUMPER	Distorted	1,268.00 FL	*843.00 FL
19	1		*REAR BUMPER RETAINER (L+R)	N/S Bent	258.00 FL	*35.00 FL
20	1		*REAR BUMPER CENTER BRACKET (NPA)	No such part	0.00 FL	*- FL
21	1		*REAR BUMPER REINFORCEMENT BAR	Bent	789.00 FL	*245.00 FL
22	2		*REAR BUMPER BRACKET (L+R)	No such part	492.00 FL	*- FL
23	1		*REAR BUMPER BEAM TOP	Bent	743.00 FL	*105.00 FL
24	1		*REAR BUMPER SPONGE	No such part	361.00 FL	*- FL
25	2		*REAR BUMPER REFLECTOR (L+R)	Cracked	282.00 FL	*64.00 FL
26	2		*REAR BUMPER CARPLATE LAMP (L+R)	Not Necessary	256.00 FL	*- FL
27	1		*REAR BUMPER TOW COVER	Torn	85.00 FL	*28.00 FL
28	2		*REAR FENDER (L+R)	Repair	5,172.00 FL	*- FL
29	1		*REAR FENDER INNER TRIM (L+R)	N/S Torn	1,622.00 FL	*265.00 FL
30	2		*REAR FENDER COWLING (L+R)	Not Necessary	490.00 FL	*- FL
31	1		*END PANEL	Badly Dented	1,021.00 FL	*442.00 FL
32	1		*END PANEL TOP GARNISH	Twisted	512.00 FL	*166.00 FL
33	1		*SPAREWHEEL PANEL	Repair	1,376.00 FL	*- FL
34	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	682.00 FL	*- FL
35	1		*SPAREWHEEL PANEL TOP BOARD TOP MAT (NPA)	Not Necessary	0.00 FL	*- FL
36	1		*EXHAUST PIPE	Not Necessary	1,090.00 FL	*- FL
37	1		*EXHAUST GASKET	Not Necessary	251.00 FL	*- FL
38	2		*EXHAUST BRACKET (L+R)	Not Necessary	372.00 FL	*- FL
39	1		*EXHAUST HEAT SHIELD	Not Necessary	379.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR WINDSCREEN SEALANT	Not Necessary	300.00 FS	*- FS
41	1		*BOOTLID SPOILER	Cut	3,000.00 FS	*600.00 FS
42	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
43	4		*TAILLAMP CLIP (L+R)	Not Necessary	80.00 FS	*- FS
44	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
45	2		*REAR BUMPER REVERSE SENSOR (L+R)	Shorted	300.00 FS	*200.00 FS
46	1		*REAR BUMPER REVERSE CAMERA	Not Necessary	850.00 FS	*- FS
47	1		*REAR CARPLATE }	Broken	200.00 FS	*40.00 FS
48	1		*REAR CARPLATE FRAME }		120.00 FS	*- FS
49	2		*REAR FENDER SEALANT	Not Necessary	600.00 FS	*- FS
50	20		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
51	20		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
52	1		*END PANEL SEALANT	Necessary	250.00 FS	*50.00 FS
53	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	33,234.00	5,765.00
- List Item Discount on L Items 10.00/10.00% (S\$)	2,658.40	482.50
Total Parts (S\$)	30,575.60	5,282.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO R&R ACCIDENT AFFECTED AREA	New	3,600.00	850.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREA	New	3,000.00	1,100.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	600.00	60.00
4	TO R&R REAR BOOT MECHANISM	New	400.00	60.00
5	TO R&R REAR WINDSCREEN	New	400.00	0.00
6	TO RNR FUEL TANK TO ASSIST WORK LOAD	New	450.00	0.00
7	TO R&R UPHOLSTERY, GARNISH AND ATTACHMENT PART	New	600.00	80.00
8	TO CHECK CARPLATE LAMP AND TEST FUNCTION	New	150.00	0.00
9	TO CHECK REVERSE SENSOR AND TEST FUNCTION	New	150.00	50.00
10	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION }	New	150.00	20.00
11	TO CHECK WIRING LAYOUT AND BOOTLID THIRD BRAKE LAMP FUNCTION }	New	150.00	0.00
12	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	150.00	0.00
13	TO DO WATER LEAK TEST	New	120.00	0.00
14	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	450.00	0.00
15	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE	New	800.00	0.00
Gross Labour Cost (S\$)			11,170.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >