Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20010122/R1GS3Q2

Date: 18/02/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100411122 Claimant SMG256M Insured Vehicle No: SF1001J Vehicle No:

Date of Loss: 17/09/2020 Nature of Claim: TP Claim No: 7344176613SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMG256M Reg No:

Make & Model: VOLKSWAGEN PASSAT B8, 1.8 (A) Engine No: CJS297461

Chassis No: Reg. Date: 30/11/2018 (Man. Year: 2018) WVWZZZ3CZKE018161

Colour: Odometer: 35111 km Black

**Engine Capacity:** 1798 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm Front Right Side: Rear Right Side: Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	2,120.00	3,280.00	60.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,400.00	2,120.00	3,280.00	60.74
+ GST 7.00/7.00% (S\$)	378.00	148.40	229.60	60.74
Nett Amount (S\$)	5,778.00	2,268.40	3,509.60	60.74
+ Loss of Use (3.0 x S\$100.00/day) (S\$) + Doc/Search Fee (S\$)		300.00		
		2.00		

**Nett Liability (S\$)** 

**INSPECTION** 

Date of Assignment: 24/09/2020

Date Inspected: 24/09/2020 Inspected At: **VOLKSWAGEN GROUP** 

SINGAPORE PTE LTD 247 Alexandra Road Singapore 159934

2,570.40

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	LABOUR	New	2,520.00	840.00
3	SPRAY PAINTING	New	2,400.00	800.00
		Gross Labour Cost (S\$)	5,400.00	2,120.00
	Report wa	is unsubmitted during this print-out.		

< END OF ESTIMATES >