

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG20010124/AES3Q2

Date:

10/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070111033

Claimant Vehicle No : SJN3384E**Insured Vehicle No :**

SMT9642D

Date of Loss: 21/09/2020

Nature of Claim:

TP

Claim No:

7074124975SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJN3384E**

Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)

Engine No: CVK087635

Reg. Date: 30/09/2019 (Man. Year: 2019)

Chassis No:

WAUZZZF51KA076521

Colour: Blue

Odometer:

8675 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size:

245/40 R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	16,823.60	7,418.48	9,405.12	55.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,922.00	2,822.00	2,100.00	42.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,745.60	10,240.48	11,505.12	52.91
+ GST 7.00/7.00% (S\$)	1,522.19	716.83	805.36	52.91

Nett Amount (\$\$)	23,267.79	10,957.31	12,310.48	52.91
		+ Loss of Use (4.0 x S\$100.00/day) (\$\$)	400.00	
		+ Doc/Search Fee (\$\$)	2.00	
		Nett Liability (\$\$)	11,359.31	

INSPECTION

Date of Assignment: 22/09/2020

Date Inspected: 24/09/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Premium Automobiles Pte Ltd - Alexandra (HQ)
 281 Alexandra Pte Ltd, Level B2
 Singapore 159938

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,251.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	402.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE LOWER CENTER	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER	Not Necessary	225.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE RH	Not Necessary	62.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	2,300.00 FS	*- FS
8	2		*FRONT BUMPER ULTRASOUND SENSOR SUPPORT	Not Necessary	102.00 FS	*- FS
9	1		*RADIATOR GRILLE UPPER COVER	Not Necessary	187.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	468.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE -RH	Not Necessary	36.00 FS	*- FS
12	1		*FRONT FENDER -RH	Dented	1,048.00 FS	*838.40 FS
13	1		*FRONT FENDER ATTACHMENT PART	Not Necessary	53.00 FS	*- FS
14	1		*FRONT FENDER CLOSING ELEMENT -RH FRT	Deformed	73.00 FS	*58.40 FS
15	1		*FRONT FENDER BRACKET -RH FRT	Not Necessary	70.00 FS	*- FS
16	1		*SET FRONT FENDER RIVET	Necessary	16.00 FS	*12.80 FS
17	1		*FRONT FENDER BRACKET -RH CENTRE	Not Necessary	35.00 FS	*- FS
18	1		*FRONT FENDER BRACE -RH FRT	Bent	117.00 FS	*93.60 FS
19	1		*FRONT FENDER DEFORMATION BRACKET -RH	Not Necessary	49.00 FS	*- FS
20	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	272.00 FS	*- FS
21	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
22	1		*FRONT WHEEL SPOILER -RH	Not Necessary	73.00 FS	*- FS
23	1		*FRONT WHEEL SPOILER TRIM -RH LOWER	Not Necessary	36.00 FS	*- FS
24	1		*FRONT FENDER STONE CHIP GUARD -RH	Not Necessary	50.00 FS	*- FS
25	1		*FRONT FENDER TRIM -RH UPPER	Not Necessary	35.00 FS	*- FS
26	1		*HEADLIGHT TRIM -RH UPPER	Not Necessary	16.00 FS	*- FS
27	1		*LED HEADLIGHT -RH	Cracked	7,812.00 FS	*6,249.60 FS
28	1		*HEADLIGHT WASHER CYLINER -RH	Not Necessary	196.00 FS	*- FS
29	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
30	1		*SUNDRIES	Necessary	300.00 FS	*40.08 FS
31	1		*FRONT FENDER CHROME TRIM RHS	Necessary	125.60 FS	*125.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)**16,823.60****7,418.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARENSS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT ,RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,650.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,922.00	2,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >