

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20010126/UVF3E2
Date: 02/10/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900100170
Claimant Vehicle No :	SLZ5928L	Insured Vehicle No :	SDN8410B
Date of Loss:	17/09/2020	Nature of Claim:	TP
		Claim No:	8543074504SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ5928L	Engine No:	L15B5461753
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81201490
Reg. Date:	10/05/2018 (Man. Year: 2018)	Odometer:	117908 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,059.73	3,046.64	7,013.09	69.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,930.00	1,970.00	5,960.00	75.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,989.73	5,016.64	12,973.09	72.11
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	17,989.73	4,000.00	13,989.73	77.77
+ GST 7.00/7.00% (S\$)	1,259.28	280.00	979.28	77.77
Nett Amount (S\$)	19,249.01	4,280.00	14,969.01	77.77

INSPECTION

Date of Assignment:	22/09/2020	
Date Inspected:	23/09/2020 Inspected At:	Kaizen Motors Pte Ltd (HQ) 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT Singapore 417896
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE ASSY	Badly Dented	1,153.00 F	*1,153.00 FL
2	2		*REAR TAIL GATE HINGE	Not Necessary	100.00 F	*- FL
3	1		*REAR TAIL GATE LOCKING MECHANISM	Dented / Shorted	276.70 F	*276.70 FL
4	1		*REAR TAIL GATE LOCKING PIN	Not Necessary	51.20 F	*- FL
5	1		*SET REAR WINDSCREEN MOULDING	Necessary	180.00 F	*78.10 FL
6	1		*REAR HONDA EMBLEM CHROME GARNISH	Not Necessary	360.50 F	*- FL
7	1		*REAR HONDA EMBLEM	Necessary	35.00 F	*35.00 FL
8	1		*REAR SHUTTLE EMBLEM	Necessary	45.00 F	*45.00 FL
9	1		*REAR LICENSE PLATE & BRACKET	Bent	100.00 FS	*40.00 FS
10	2		*REAR TAIL LAMP UPPER ASSY	Not Necessary	760.00 F	*- FL
11	2		*REAR TAIL LAMP LOWER ASSY	Not Necessary	560.00 F	*- FL
12	1		*REAR BUMPER ASSY	Dented / Deformed	922.10 F	*922.10 FL
13	2		*REAR BUMPER BRACKET	No such part	90.00 F	*- FL
14	1		*REAR SUPPORT PANEL	No such part	765.00 F	*- FL
15	1		*REAR END PANEL	Dented	570.00 F	*570.00 FL
16	1		*REAR END PANEL GARNISH	Deformed	338.20 F	*215.10 FL
17	1		*REAR END PANEL WEATHERSTRIP	Twisted	163.30 F	*163.30 FL
18	1		*REAR END PANEL INNER SIDE TRIM	Not Necessary	180.80 F	*- FL
19	1		*REAR INFORCEMENT BEAM	No such part	635.33 F	*- FL
20	2		*REAR FENDER ASSY	Repair	1,681.60 F	*- FL
21	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
22	20		*REAR END PANEL SIDE TRIMMING CLIPS	Not Necessary	80.00 FS	*- FS
23	8		*REAR END PANEL GARNISH CLIPS	Not Necessary	32.00 FS	*- FS
24	1		*REAR PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
25	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,059.73 3,738.30
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 691.66

Total Parts (\$\$) 10,059.73 3,046.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR CHECKING ON WIRING	New	120.00	30.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF END PANEL, SUPPORT PANEL, REAR TAIL GATE, REAR BUMPER ASSY, REAR TAIL LAMP LOWER & UPPER ASSY & HINGES	New	2,800.00	700.00
3	LABOUR FOR REPLACING OF WINDSCREEN, WIPER ARM, MOTOR, EMBLEM, LICENSE PLATE	New	1,800.00	120.00
4	LABOUR FOR PANEL BEATING OF ROOF, REMOVING & INSTALLING OF ROOF TRIMMING	New	650.00	80.00
5	SPRAY PAINTING & PUTTY OF END PANEL, SUPPORT PANEL, TAIL GATE, BUMPER, FENDER & ROOF	New	1,900.00	900.00
6	LABOUR FOR RETROFITTING MOULDING & WEATHERSTRIP UPHOLSTERY	New	250.00	80.00
7	LABOUR FOR APPLYING RUST-PROOFING	New	250.00	60.00
8	WHEEL ALIGNMENT	New	160.00	0.00
Gross Labour Cost (\$\$)			7,930.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >