Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010128/ATF3Q2

Date: 09/12/2020

REFERENCE

China Taiping Insurance Policy No: Handling Insurer:

(Singapore) Pte. Ltd.

DMCVSNA00015592001

Claimant Vehicle No:

SMF9210R

Insured Vehicle No:

GBE8396E

Date of Loss:

19/09/2020

Nature of ΤP

Claim:

Claim

SNM20D203448/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF9210R**

Make & Model: AUDI A1 SPORTBACK, 1.0 TFSI S-tronic (A)

CHZB20180 Engine No:

Reg. Date: 29/11/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V9KA004379 Odometer: 14674 km

Colour: Grey **Engine Capacity:** 999 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 205/55R16 205/55R16 Rear Tyre Size: Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,162.00	1,847.00	1,315.00	41.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,422.00	1,872.00	550.00	22.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,584.00	3,719.00	1,865.00	33.40
+ GST 7.00/7.00% (S\$)	390.88	260.33	130.55	33.40
Nett Amount (S\$)	5,974.88	3,979.33	1,995.55	33.40

INSPECTION

Date of Assignment: 22/09/2020

Date Inspected: 24/09/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: DENISE TAY KWEE CHENG Manager: ADRIAN LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Dec 2020)

Parts: 144 AUDI A1 SPORTBACK 1.0 TFSI S-tronic (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF9210R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

0----

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,847.00 FS	*1,847.00 FS
2	2		*REAR BUMPER STICKY PAD	Not Necessary	12.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
4	2		*REAR BUMPER LOCKING MECHANISM-LH/RH	Not Necessary	28.00 FS	*-FS
5	1		*REAR BUMPER SPOILER	Not Necessary	234.00 FS	*-FS
6	1		*REAR LIGHT REFLECTOR-RH	Not Necessary	30.00 FS	*-FS
7	1		*REAR REINFORCEMENT BEAM	Not Necessary	565.00 FS	*- FS
8	1		*REAR BUMPER BRACKET-LH	Not Necessary	27.00 FS	*-FS
9	1		*REAR BUMPER BRACKET-RH	Not Necessary	28.00 FS	*- FS
10	1		*SUNDRIES	Not Necessary	200.00 FS	*-FS
F=Fra	anchise	part. S=Spc	Nett.			
				Total Parts (S\$)	3,162.00	1,847.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00				
2	TO DISMANTLE AND RENEW REAR BUMPER.RE- ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	700.00				
3	TO RESPRAY REAR BUMPER	New	900.00	700.00				
4	TO REAPPLY PAINT COATING ON REAR BUMPER (BY OWNER)	New	0.00	0.00				
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00				
	Gross Labor	ur Cost (S\$)	2,422.00	1,872.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >