

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX

SINGAPORE 069110

INV No. AC2104101

INV Date 11/06/2021

Reference CC3/EQI20010129/Apa3q2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SLR 4765M

Insured Veh. SKP 5546U

Claim No. DM20HO01366/JT

Policy No. DMPPHQ19-006028

Accident Date 15/09/2020

Inspection Date 18/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		1.0g. 1.0000	1301. OOT 1.0g. 140. 13 30						
	Affiliated to Federation Internationale Des Experts En Automobile								
	EQ INSURANCE O	COMPANY LTD	Ref:	CC3/EQI20010129/Apa3q2					
	5 MAXWELL ROAL		Date	11/06/2021					
	#17-00 TOWER BL	NGAPORE 069110							
			Code	e: EQI					
1.		Policy Particulars	:- THIRD PARTY CLA	IM					
	Insured Veh.	SKP 5546U	Veh. Inspected	SLR 4765M					
	Policy No.	DMPPHQ19-006028	Coverage (\$)	0.00					
	Claim No.	DM20HO01366/JT	Excess (\$)	0.00					
	Assign From		Assign Date	18/09/2020					
2.	2. Vehicle Particulars & Condition								
	Make & Model	AUDI Q2	c.c	999					
	Engine No.	HIDDEN	Year of Reg.	2017					
	Chassis No.	WAUZZZGA9JA001351	Colour	GREY					
	Odometer	38307 KM	Steering	IN ORDER					
	Brakes	IN ORDER	Modification	SPORTS RIM					
	General	GOOD							
3.		Conditi	ons of Tyres						
		Size	Make	Balance					
	R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm					
	L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm					
	R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm					
	L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm					
4.		Description	on of Damages						
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	AR O/S PORTION.						
	DAMAGES SEE D	ETAILS.							
-		2	Llufama Can						
5.	la		I Information	40/00/0000					
	Accident Date	15/09/2020	Inspection Date	18/09/2020					
	Survey held at	Survey held at PREMIUM AUTOMOBILES PTE LTD							
		55 UBI ROAD 1 . SINGAPORE 408699							
5a.		R	emarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.								
5b.									
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days								



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 4765M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (SN)	TO REPAIR SEE LABOUR	1,164.00	-
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	76.00	-
1	REAR BUMPER SPOILER (SN)	NOT NECESSARY	281.00	-
1	REAR BUMPER TOWING EYE COVER (SN)	NOT NECESSARY	43.00	-
1	REAR LIGHT REFLECTOR -RH (SN)	NOT NECESSARY	30.00	-
1	TAIL LIGHT (SN)	NOT NECESSARY	1,306.00	-
1	TAIL LIGHT TRIM (SN)	NOT NECESSARY	30.00	-
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	544.00	-
2	REAR BUMPER HOLDING STRAP -LH /RH (SN)	NOT NECESSARY	26.00	-
1	REAR PARKING AID SENSOR -OUTER (SN) (NPA)	NOT NECESSARY	-	-
4	REAR PARKING AID SEAL RING (SN)	NOT NECESSARY	14.00	-
2	REAR WHEEL COVER -LH/RH (SN)	NECESSARY	336.00	336.00
1	SUNDRIES (SN)	NOT NECESSARY	200.00	-
			4,050.00	336.00
	<u>LABOUR</u>			
	TO REMOVE AND TRANSFER REAR PARKING AID ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.		280.00	280.00
	TO DISMANTLE AND RENEW REAR BUMPER .RE- ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		1,200.00	800.00
	TO RESPRAY REAR BUMPER .		1,000.00	800.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			2,672.00	2,072.00
	GRAND TOTAL		6,722.00	2,408.00

Report Ref No. CC3/EQI20010129/Apa3q2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 2,408.00

Report Ref No. CC3/EQI20010129/Apa3q2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replyin

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 4765M

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 4765M

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







