

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010130/EVF3E2

Date: 02/11/2020

REFERENCE

Insured/Claimant:	CHIN LEONG YONG	Policy No:	2100467555	
Date of Loss:	19/09/2020	Nature of Claim:	OD	Claim No: 1582909198SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDK6168E		
Make & Model:	KIA FORTE K3, 1.6 SX (A)	Engine No:	G4FGFH608138
Reg. Date:	27/05/2016 (Man. Year: 2015)	Chassis No:	KNAFZ411MG5570090
Colour:	Blue	Odometer:	49476 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$53,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R16	Rear Tyre Size:	195/55R16
Front Left Side:	Firestone 5 mm	Rear Left Side:	Firestone 5 mm
Front Right Side:	Firestone 5 mm	Rear Right Side:	Firestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,245.20	8,994.00	1,251.20	12.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,110.00	6,160.00	2,950.00	32.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,355.20	15,154.00	4,201.20	21.71
Approved Total (Overridden) (\$\$)		13,000.00		
(\$\$)	19,355.20	13,000.00	6,355.20	32.83
+ GST 7.00/7.00% (\$\$)	1,354.86	910.00	444.86	32.83
Nett Amount (\$\$)	20,710.06	13,910.00	6,800.06	32.83

INSPECTION

Date of Assignment:	22/09/2020	
Date Inspected:	22/09/2020 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER	Dented	791.00 FL	*791.00 FL
2	1		*COVER-RR BUMPER,UPR	Broken	245.00 FL	*245.00 FL
3	1		*COVER-RR BPR UNDER	Missing	42.00 FL	*42.00 FL
4	1		*WIRING HARNESS-BWS EXT	Not Necessary	173.00 FL	*- FL
5	1		*BEAM-RR BUMPER	Broken	365.00 FL	*365.00 FL
6	1		*BRACKET-RR BEAM LWR MTG (2 Pcs)	Broken (1 Pcs only)	10.00 FL	*5.00 FL
7	1		*BRACKET-RR BEAM LWR,CTR	Broken	5.00 FL	*5.00 FL
8	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	69.00 FL	*- FL
9	1		*BRACKET-RR RAIL UPR MTG,RH	Bent	4.00 FL	*4.00 FL
10	1		*BRACKET-RR RAIL UPR MTG,LH	Not Necessary	4.00 FL	*- FL
11	1		*STAY-RR BUMPER RH	Broken	75.00 FL	*75.00 FL
12	1		*STAY-RR BUMPER LH	Not Necessary	75.00 FL	*- FL
13	1		*BRACKET-RR BUMPER SIDE MTG,RH	Broken	33.00 FL	*33.00 FL
14	1		*BRACKET-RR BUMPER SIDE MTG,LH	Not Necessary	33.00 FL	*- FL
15	1		*PANEL ASSY-TRUNK LID	Dented	1,365.00 FL	*1,365.00 FL
16	1		*HINGE ASSY-TRUNK LID,RH	Bent	68.00 FL	*68.00 FL
17	1		*PANEL ASSY-BACK	Dented	372.00 FL	*372.00 FL
18	1		*PNL ASSY-RR FLOOR RR COMPLETE	Dented	602.00 FL	*602.00 FL
19	1		*PANEL ASSY-RR COMB LAMP HSG,RH	Bent	123.00 FL	*123.00 FL
20	1		*TRIM T/LID	Not Necessary	82.00 FL	*- FL
21	1		*LATCH ASSY-TRUNK LID	Bent	112.00 FL	*112.00 FL
22	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 FL	*100.00 FL
23	1		*LOGO ASSY-KIA SUB	Necessary	37.00 FL	*37.00 FL
24	1		*EMBLEM-CERATO	Necessary	35.00 FL	*35.00 FL
25	1		*TRIM-TRANSVERSE RR	Broken	58.00 FL	*58.00 FL
26	1		*MAT ASSY-LUGGAGE COVERING	Not Necessary	159.00 FL	*- FL
27	1		*TRIM ASSY-LUGGAGE SIDE RH	Crushed	161.00 FL	*161.00 FL
28	1		*SPOILER-RR	Not Necessary	590.00 FL	*- FL
29	1		*LAMP ASSY-REAR COMB INSIDE,RH	Cut	710.00 FL	*710.00 FL
30	1		*LAMP ASSY-REAR COMB INSIDE,LH	Cut	710.00 FL	*710.00 FL
31	1		*LAMP ASSY-REAR COMBINATION,RH	Broken	843.00 FL	*843.00 FL
32	1		*LAMP ASSY-REAR COMBINATION,LH	Cut	843.00 FL	*843.00 FL
33	1		*ULTRASONIC SENSOR ASSY-FBWS (4 Pcs)	Broken (2 Pcs only)	748.00 FL	*374.00 FL
34	1		*MUFFLER ASSY-REAR	Bent	729.00 FL	*729.00 FL
35	1		*PROTECTOR-HEAT REAR	Bent	60.00 FL	*60.00 FL
36	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
37	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
38	1		*REAR NUMBER PLATE WITH FRAME	Cut	50.00 FS	*50.00 FS
39	1		*MUFFLER COMPLETE-CENTER	Bent	615.00 FL	*615.00 FL
40	1		*PANEL ASSY-RR COMB LAMP HSG,RH	Dented	123.00 FL	*123.00 FL
41	1		*PANEL ASSY-QUARTER OUTER,RH	Dented	1,213.00 FL	*1,213.00 FL
42	1		*GRILLE ASSY-AIR EXTRACTOR	Missing	32.00 FL	*32.00 FL
43	2		*MOUNTING CLIP-REAR COMBI	Necessary	10.00 FL	*10.00 FL
44	10		*CLIP	Necessary	20.00 FL	*20.00 FL
45	1		*FILM-ANTI CHIPPG RH	Necessary	27.00 FL	*27.00 FL
46	2		*SILENCER,FLOOR	Necessary	26.00 FL	*26.00 FL
47	1		*GUARD-BUMPER REAR,RH	Necessary	17.00 FL	*17.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*MOULDING-REAR WINDOW GLASS	Necessary	27.00 FL	*27.00 FL
49	10		*PAD-WINDSHIELD GLASS	Necessary	20.00 FL	*20.00 FL
50	2		*STOPPER-RR WINDOW GLASS	Necessary	8.00 FL	*8.00 FL
51	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,759.00	11,195.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,513.80	2,201.00
Total Parts (\$\$)	10,245.20	8,994.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & INSTALL PARKING SENSOR	New	300.00	60.00
2	REMOVE & INSTALL REAR COMPARTMENT TRIMS,SEATS	New	300.00	240.00
3	SPRAY PAINT FOR REAR BUMPER,END PANEL,BOOTLID,REAR COMPARTMENT REAR LAMP HOUSING RH,REAR FENDER RH,SPOILAR	New	2,800.00	1,750.00
4	RENEW REAR BUMPER,BOOTLID,REAR END PANEL,REAR COMPARTMENT REAR LAMP HOUSING RH,SPOILAR,REPAIR REAR FENDER RH,REAR CHASSIS RH	New	3,600.00	3,200.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY SEALANT FOR ACCIDENT PORTION	New	120.00	120.00
8	RENEW EXHAUST SYSTEM	New	400.00	200.00
9	TO MOUNT VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS ALIGNMENT	New	1,000.00	0.00
10	REMOVE & INSTALL FUEL TANK	New	200.00	200.00
11	REMOVE & REFIT REAR WINDSCREEN GLASS	New	240.00	240.00
Gross Labour Cost (\$\$)			9,110.00	6,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >