

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20010135/KPS3Q2  
**Date:** 30/03/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100507448
<b>Claimant Vehicle No :</b>	SMD5390R	<b>Insured Vehicle No :</b>	SJE1496B
Date of Loss:	17/09/2020	Nature of Claim:	TP
		Claim No:	1853391529SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMD5390R</b>	Engine No:	27682130597722
Make & Model:	MERCEDES-BENZ GLE400, 3.0 4MATIC (A)	Chassis No:	WDC2923562A078671
Reg. Date:	24/08/2018 (Man. Year: 2017)	Odometer:	14338 km
Colour:	Metallic Pearl White		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/45 R21	Rear Tyre Size:	315/40 R21
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Continental 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,921.61	10,692.99	6,228.62	36.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,500.00	2,090.00	58.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,511.61</b>	<b>12,192.99</b>	<b>8,318.62</b>	<b>40.56</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,700.00</b>		
	(S\$)	20,511.61	9,700.00	10,811.61
	<b>+ GST 7.00/7.00% (S\$)</b>	1,435.81	679.00	756.81
	<b>Nett Amount (S\$)</b>	<b>21,947.42</b>	<b>10,379.00</b>	<b>11,568.42</b>
	<b>+ Car Rental (4.0 x S\$140.00/day + 7.00% GST) (S\$)</b>		599.20	
	<b>+ Doc/Search Fee (S\$)</b>		2.00	
	<b>Nett Liability (S\$)</b>		<b>10,980.20</b>	
	<b>Global Sum Settlement (S\$)</b>		<b>10,900.00</b>	

### INSPECTION

Date of Assignment:	22/09/2020		
Date Inspected:	28/09/2020	Inspected At:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days		

---

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Repair	1,899.00 FL	*- FL
2	1		*FRONT RH FENDER WHEEL ARCH MOULDING	Dented	257.00 FL	*257.00 FL
3	1		*FRONT BUMPER	Buckled / Cut	2,037.00 FL	*1,812.00 FL
4	1		*FRONT BUMPER RH LOWER COVER	Serviceable	175.00 FL	*- FL
5	1		*FRONT BUMPER RH LOWER GRILLE	Serviceable	157.00 FL	*- FL
6	1		*FRONT BUMPER RH SIDE RETAINER	Serviceable	166.00 FL	*- FL
7	1		*FRONT BUMPER CENTER LOWER CARRIER	Repair	510.00 FL	*- FL
8	1		*FRONT BUMPER SPONGE	Serviceable	237.50 FL	*- FL
9	1		*HEADLAMP RH	Cut	5,108.40 FL	*4,610.10 FL
10	1		*FRONT RH RIM	Dented	2,871.00 FL	*2,100.00 FL
11	1		*FRONT RH KNUCKLE ARM	Bent	1,152.00 FL	*1,152.00 FL
12	1		*FRONT RH KNUCKLE ARM BEARING	Necessary	990.00 FL	*624.00 FL
13	1		*FRONT RH UPPER ARM	Serviceable	882.00 FL	*- FL
14	1		*FRONT RH LOWER ARM	Distorted	1,404.00 FL	*1,206.00 FL
15	1		*FRONT RH SHOCK ABSORBER	Serviceable	747.00 FL	*- FL
16	15		*RIVETS	Necessary	120.00 FL	*120.00 FL
17	1		*BODY SEALANT	Serviceable	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>18,792.90</b>	<b>11,881.10</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,871.29	1,188.11
<b>Total Parts (\$)</b>	<b>16,921.61</b>	<b>10,692.99</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REFIT &REPAIR AFFECTED DAMAGED PARTS INCLUDING TO KNOCK -OUT WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	500.00
2	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	100.00	60.00
3	TO REMOVE & REPLACE FRONT RH UNDERCARRIAGE	New	350.00	200.00
4	TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	New	300.00	0.00
5	TO APPLY ANTI RUST COATING	New	150.00	0.00
6	TO REMOVE ,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
7	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	60.00
8	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
9	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	660.00
<b>Gross Labour Cost (S\$)</b>			<b>3,590.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >