

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20010137/T1SD3E2

Date: 09/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100480201
Claimant Vehicle No : SMT685P	Insured Vehicle No : SFU8555G
Date of Loss: 13/09/2020	Nature of Claim: TP Claim No: 2967488649SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT685P		
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Engine No:	LEB1438465
Reg. Date:	26/03/2020 (Man. Year: 2018)	Chassis No:	GP51332064
Colour:	White	Odometer:	28302 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,928.10	2,042.56	2,885.54	58.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,470.00	1,230.00	45.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,628.10	3,512.56	4,115.54	53.95
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	7,628.10	2,800.00	4,828.10	63.29

INSPECTION

Date of Assignment: 22/09/2020
 Date Inspected: 23/09/2020 Inspected At:

Hup Ley Huat Motor Spray Painting
 Services - Kaki Bukit (HQ)
 BLK 1 KAKI BUKIT AVENUE 6, #01-35
 Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	492.60 F	*492.60 FL
2	1		*REAR BUMPER RETAINER RH	Necessary	16.90 F	*16.90 FL
3	1		*REAR BUMPER RETAINER LH	Necessary	16.90 F	*16.90 FL
4	1		*REAR BUMPER REFLECTOR LH	Not Necessary	48.00 F	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Not Necessary	48.00 F	*- FL
6	1		*REAR BUMPER STRIP GARNISH	Cracked	65.00 F	*65.00 FL
7	1		*REAR BOOTLID INNER TRIMBOARD	Cracked	422.00 F	*422.00 FL
8	1		*REAR BOOT LID	Bent	880.00 F	*880.00 FL
9	1		*REAR BOOT LID COVER	Not Necessary	98.00 F	*- FL
10	1		*REAR BOOT LID WEATHER STRIP	Not Necessary	92.30 F	*- FL
11	1		*REAR BOOT LOCK	Bent	151.70 F	*151.70 FL
12	1		*REAR WINDSCREEN SEALANT	Necessary	180.00 F	*60.00 FL
13	1		*REAR CAMERA	Not Necessary	1,041.00 F	*- FL
14	1		*REAR END PANEL	Repair	320.00 F	*- FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	120.60 F	*120.60 FL
16	1		*REAR EXHAUST	Repair	430.10 F	*- FL
17	1		*SET REAR EMBLEM	Necessary	40.00 F	*40.00 FL
18	1		*LHS REAR WHEELHOUSE SHIELD	Not Necessary	35.00 F	*- FL
19	1		*RHS REAR WHEELHOUSE SHIELD	Not Necessary	35.00 F	*- FL
20	1		*REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
21	1		*REAR REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,928.10	2,495.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	453.14
Total Parts (\$\$)	4,928.10	2,042.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIR PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
2	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	150.00	30.00
3	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD, RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
4	TO REMOVE AND REFIT WINDSCREEN	New	200.00	120.00
5	TO REMOVE AND REFIT REVERSE SENSOR	New	120.00	30.00
6	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR	New	150.00	60.00
7	TO REMOVE, REFIT, REPLACE DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
Gross Labour Cost (S\$)			2,700.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >