

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010138/AVF3Q2

Date: 05/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00029952003
Claimant Vehicle No :	SDM8858Z	Insured Vehicle No :	SKW1260H
Date of Loss:	13/09/2020	Nature of Claim:	TP
		Claim No:	SNM20D203411/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDM8858Z		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX012912
Reg. Date:	27/09/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF3H2048510
Colour:	Black	Odometer:	20948 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,747.00	1,982.50	6,764.50	77.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	3,352.00	1,200.00	26.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,299.00	5,334.50	7,964.50	59.89
+ GST 7.00/7.00% (\$\$)	930.93	373.42	557.51	59.89
Nett Amount (\$\$)	14,229.93	5,707.92	8,522.01	59.89

INSPECTION

Date of Assignment:	28/09/2020	
Date Inspected:	25/09/2020	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Feb 2021)
Parts:	M1-SUV	AUDI Q5 SPORT 2.0 TFSI QU S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDM8858Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR UPPER BUMPER	Repair	1,724.00 FS	*- FS
2	1		*REAR LOWER BUMPER	Repair	1,182.00 FS	*- FS
3	1		*REAR SPOILER	Cut	830.00 FS	*829.50 FS
4	1		*REAR BUMPER TOWING EYE COVER-LH	Not Necessary	48.00 FS	*- FS
5	1		*REAR BUMPER TOWING EYE COVER-RH	Not Necessary	29.00 FS	*- FS
6	2		*REAR BUMPER CLOSING ELEMENT-LH/RH	Not Necessary	190.00 FS	*- FS
7	2		*REAR BUMPER TRIM-LH/RH	Not Necessary	468.00 FS	*- FS
8	2		*TAIL LIGHT-LH/RH	Not Necessary	1,382.00 FS	*- FS
9	1		*BOOT LID CONTROL UNIT	Not Necessary	399.00 FS	*- FS
10	1		*REAR BUMPER CARRIER	Not Necessary	911.00 FS	*- FS
11	1		*REAR BUMPER HOLDING STRAP	Not Necessary	166.00 FS	*- FS
12	2		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
13	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
14	2		*REAR WHEEL COVER-LH/RH	Necessary	1,154.00 FS	*1,153.00 FS
15	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
Total Parts (\$\$)					8,747.00	1,982.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	800.00
3	TO RESPRAY REAR TOP BUMPER,REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	2,800.00	2,000.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,552.00	3,352.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >