

# FIRE REPORT

### 

#### 2. INCIDENT INFORMATION

FIRE INVOLVED: The engine compartment of a Isuzu lorry (YN3808Y).

METHOD OF EXTINGUISHMENT: By SCDF crew using a 38mm hose line jet from fire appliance.

PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the engine compartment)

DAMAGE SUSTAINED: As a result of the fire, the engine and front part of the lorry including the cabin were damaged. Part of the side panels and timber decking of the carriage deck were also damaged.

#### 3. FATALITY/INJURY INFORMATION

NAME	PIN/FIN		DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL

## REPORT CERTIFIED TRUE AND CORRECT BY:

MUHAMMAD FAIZAL BIN MAZLAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE

This is a computer generated Fire Report. No signature is required.