



Service Request Details

Claim

S0M02U1Z

Reference

None

Loss Date

September 17, 2020

Report Date

Sep 22, 2020 9:05:31 AM

Request Date

September 22, 2020

Due Date

September 22, 2021

Vendor Name

LKK AUTO CONSULTANTS
PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop
survey

Actions

Next Step

Finish the work

Complete
Work

More

Vehicle Information

Incident Vehicle

Registration #

YN3808Y

Make

ISUZU

Model

NPR75UH5AC

Service Address

51 Ubi Avenue 1 #01-25

Paya Ubi, , 408933

Primary Contact

Primary

Contact/Insured

ENTREPOT ONE PTE
LTD2 BUKIT MERAH
CENTRAL, #20-01,
159835, Singapore
65674755

HONGYEN.CHONG@ALLINK.COM

Claim Handler

ANG Yvonne

6568804461

yvonne.ang@axa.com.sg

Quote

Total Amount

Status

View Quote

Add Quote

Insured

ENTREPOT
ONE PTE LTD 2
BUKIT MERAH
CENTRAL, #20-01,
159835,
Singapore 65674755
HONGYEN.CHONG@ALLINK.COM.SG

Additional Instructions

ASM FIRE DAMAGE PLEASE SURVEY WP AND CONDUCT FIRE INVESTIGATION

(expand)

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Upload Documents

Already Attached

NAME

[LOG CARD.pdf](#)

TYPE

Forms / Claim Documents

SUB-TYPE

Internal Advice

AUTHOR

ANG Yvonne

DATE UPLOADED

September 22, 2020

NAME

[GA517904-Policy Schedule.pdf](#)

TYPE

Forms / Claim Documents

SUB-TYPE

Policy Schedule / Covernote / Certificate of insurance

AUTHOR

PODUVAL Akash

DATE UPLOADED

September 22, 2020

NAME

[GA517904-Certificate of Insurance.pdf](#)

TYPE

Forms / Claim Documents

SUB-TYPE

Policy Schedule / Covernote / Certificate of insurance

AUTHOR

PODUVAL Akash

DATE UPLOADED

September 22, 2020

NAME	YN3808Y INSD GIA REPORT.PDF
TYPE	Reports & Statement
SUB-TYPE	GIA Report
AUTHOR	PODUVAL Akash
DATE UPLOADED	September 22, 2020

NAME	OD PRI FROM WORKSHOP.pdf
TYPE	Letters and Correspondence
SUB-TYPE	Workshop
AUTHOR	PODUVAL Akash
DATE UPLOADED	September 22, 2020
