Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19021067/R1QF3E2

Date: 30/11/2020

**REFERENCE** 

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMB1SN19251719000

TP

Claimant Vehicle YP8264Y

Insured Vehicle No:

PC6965X

Date of Loss: 17/11/2019 Nature of Claim:

Claim

No:

Chassis No:

SNM19D205658/PC6965X/TKL

JHHUCS3H60K022754

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: YP8264Y

Make & Model: HINO XZU710R-HKFMS3, 4.0 D (M)

Engine No: N04CUS34694

Reg. Date: 28/12/2017 (Man. Year: 2017)

Odometer: 128220 km

Colour: White 4009 cc

**Engine Capacity:** Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16 Rear Tyre Size: 7.00 R16(D) Front Left Side: Sumitomo 7 mm Rear Left Side: Sumitomo 7/7 mm Sumitomo 7 mm Rear Right Side: Sumitomo 7/7 mm Front Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	3,805.00	-3,805.00	
Miscellaneous Items	6,500.00	0.00	6,500.00	100.00
Labour	1,600.00	1,000.00	600.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,100.00	4,805.00	3,295.00	40.68
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	8,100.00	3,850.00	4,250.00	52.47
+ GST 7.00/7.00% (S\$)	567.00	269.50	297.50	52.47
Nett Amount (S\$)	8,667.00	4,119.50	4,547.50	52.47

**INSPECTION** 

Date of Assignment: 28/11/2019 Present Location: Cheng Auto Bodyworks (HQ) Date Inspected: 29/09/2020 Inspected At: Chena Auto Bodyworks (HQ)

5 Soon Lee Street #01-62 Pioneer Point

Singapore 627607

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Part Source: (Last Synchronised: 30 Nov 2020)

Parts: N/A HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP8264Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILDOOR RH	Cut	-	*2,500.00 FL
2	1		*TAILDOOR HINGE RH UPPER	Bent	-	*150.00 FL
3	1		*TAILDOOR HINGE RH LOWER	Serviceable	-	*-FL
4	4		*TAILDOOR RUBBER RH	Cut	-	*800.00 FL
5	1		*TAILDOOR SIDE ALUMINIUM PANEL RH	Serviceable	-	*-FL
6	1		*TAILDOOR INNER CHESSPLATE	Serviceable	-	*-FL
7	1		*HINGE BOLTS	Serviceable	-	*-FL
8	1		*STICKER RH REAR	Not Necessary	-	*-FL
9	1		*STICKER TAILDOOR RH	Necessary	-	*400.00 FS
10	1		*END PANEL	Bent	-	*300.00 FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items 0.00/10.00% (S\$)			<b>0.00</b> 0.00	<b>4,150.00</b> 345.00	
				Total Parts (S\$)	0.00	3,805.00
	Report was unsubmitted during this print-out.					

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Miscellaneous Items					
1	1	HINGE BOLTS		200.00	0.00
2	1	INNER TAILDOOR BOLTS		100.00	0.00
3	1	SIDE PANEL BOLTS		100.00	0.00
4	1	STICKER TAILDOOR RH		1,200.00	0.00
5	1	TAILDOOR HINGE RH LOWER		300.00	0.00
6	1	TAILDOOR HINGE RH UPPER		300.00	0.00
7	1	TAILDOOR INNER CHESSPLATE		800.00	0.00
8	1	TAILDOOR RH		2,500.00	0.00
9	1	TAILDOOR RUBBER RH		200.00	0.00
10	1	TAILDOOR SIDE ALUMINIUM PANEL RH		800.00	0.00
			Sub Total (S\$)	6.500.00	0.00

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	Labour Items					
1	LABOUR	New	800.00	500.00		
2	SPRAYPAINTING	New	800.00	500.00		
		Gross Labour Cost (S\$)	1,600.00	1,000.00		

Report was unsubmitted during this print-out.

< END OF ESTIMATES >