

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 9836E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT WINDSCREEN RUBBER	SERVICEABLE	95.00	-
1	FRONT BODY PANEL	BENT	350.00	250.00
1	FRONT WIPER PANEL	TO REPAIR SEE LABOUR	130.00	-
1	FRONT RADIATOR GRILLE	CRACKED	185.00	185.00
1	FRONT BUMPER	BENT	230.00	230.00
1	FRONT BUMPER BRACKET RH	BENT	85.00	85.00
1	FRONT HEADLAMP RH	MTG CRACKED	300.00	300.00
1	FRONT CHASSIS CROSS MEMBER	BENT	85.00	85.00
1	FRONT DYNA EMBLEM	NECESSARY	25.00	25.00
1	FRONT GRILLE LOGO EMBLEM	NECESSARY	28.00	28.00
6	FRONT GRILLE CLIPS - 1 @\$2.50	NECESSARY	15.00	15.00
6	FRONT GRILLE CLIPS - 2 @\$2.50	NOT NECESSARY	15.00	-
	COST PLUS 10%		154.30	120.30
			1,697.30	1,323.30
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	15.00	15.00
			15.00	15.00
	<u>LABOUR</u>			
	TO DISMANTLE + REFIX FRONT WINDSCREEN.	NOT NECESSARY	140.00	-
	TO DISMANTLE + REFIX FRONT DASHBOARD.	NOT NECESSARY	280.00	-
	TO STRAIGHTEN FRONT BODY INCLUDING CUTTING AND WELDING, TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT WIPER PANEL.		900.00	800.00
	TO SPRAY PAINT (INCLUDING BLEND CORNER PANEL LH & RH).		900.00	800.00
			2,220.00	1,600.00
	GRAND TOTAL		3,932.30	2,938.30



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		2,938.30
LESS EXCESS		-1,000.00
NETT LIABILITY		1,938.30

Report Ref No. CS/UOI20010141/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser