

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20010142/AVF3E2

**Date:** 25/01/2021

### REFERENCE

Insured/Claimant:	YEO KHEE ENG	Policy No:	1900013358		
Date of Loss:	18/09/2020	Nature of Claim:	OD	Claim No:	8431508740SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS8628G		
Make & Model:	AUDI A4, 2.0 (A)	Engine No:	CVK075735
Reg. Date:	31/01/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF49KN006460
Colour:	Grey	Odometer:	19516 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,801.00	9,780.16	17,020.84	63.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,702.00	2,822.00	1,880.00	39.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>31,503.00</b>	<b>12,602.16</b>	<b>18,900.84</b>	<b>60.00</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>30,703.00</b>	<b>11,802.16</b>	<b>18,900.84</b>	<b>61.56</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,149.21</b>	<b>826.15</b>	<b>1,323.06</b>	<b>61.56</b>
<b>Nett Amount (S\$)</b>	<b>32,852.21</b>	<b>12,628.31</b>	<b>20,223.90</b>	<b>61.56</b>

### INSPECTION

Date of Assignment:	22/09/2020		
Date Inspected:	22/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,171.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	580.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	208.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cracked	1,317.00 FS	*1,053.60 FS
7	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	268.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
10	1		*FRONT BUMPER TOP COVER	Cracked	126.00 FS	*100.40 FS
11	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
12	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
13	1		*LOCK CARRIER BRACKET	Cracked	136.00 FS	*108.40 FS
14	2		*LOCK CARRIER BRACKET SUPPORT-LH/RH	Not Necessary	56.00 FS	*- FS
15	1		*BONNET	Dented	2,763.00 FS	*2,210.40 FS
16	1		*BONNET ATTACHMENT PARTS	Not Necessary	408.00 FS	*- FS
17	2		*BONNET LID HINGE-LH/RH	Not Necessary	602.00 FS	*- FS
18	1		*BONNET IMPACT PROTECTION-CENTRE	Necessary	27.00 FS	*21.52 FS
19	1		*BONNET IMPACT PROTECTION-LH	Necessary	28.00 FS	*21.84 FS
20	1		*BONNET IMPACT PROTECTION-RH	Necessary	27.00 FS	*21.52 FS
21	2		*BONNET STRIKER-LH/RH	Not Necessary	100.00 FS	*- FS
22	2		*BONNET LID LOCK	Not Necessary	423.00 FS	*- FS
23	1		*BONNET BOWDEN CABLE-CENTRE	Not Necessary	57.00 FS	*- FS
24	1		*BONNET BOWDEN CABLE	Not Necessary	57.00 FS	*- FS
25	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
26	1		*LED HEADLIGHT-LH/RH	N/s Cracked	15,386.00 FS	*6,154.40 FS
27	2		*LIFT CYLINDER-LH/RH	Not Necessary	416.00 FS	*- FS
28	2		*RADIATOR AIR GUIDE-LH/RH	Not Necessary	56.00 FS	*- FS
29	2		*RADIATOR AIR GUIDE-LH/RH	Deformed	24.00 FS	*9.36 FS
30	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	16.00 FS	*- FS
31	1		*RADIATOR AIR GUIDE-LOWER	Not Necessary	22.00 FS	*- FS
32	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
33	1		*SUNDRIES	Necessary	250.00 FS	*2.24 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **26,801.00**    **9,780.16**

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES	New	700.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,BOTH HEADLIGHTS.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,650.00	1,000.00
4	TO RESPRAY FRONT BUMPER,BONNET AND HINGES	New	1,600.00	1,100.00
5	TO TOW BACK VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,702.00</b>	<b>2,822.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >