

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20010150/T1YF3E2

Date: 29/09/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT109961

Claimant Vehicle No : SHC394C

Insured Vehicle No : GBF5186J

Date of Loss: 20/09/2020

Nature of Claim: TP

Claim No: M2004650

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC394C**

Make & Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR2C12862

Reg. Date: 02/05/2019 (Man. Year: 2018)

Chassis No: JTDKB3FU503080277

Colour: Yellow

Odometer: 127314 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No

Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Davanti 6 mm

Rear Left Side: Davanti 6 mm

Front Right Side: Davanti 6 mm

Rear Right Side: Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,414.80	982.12	432.68	30.58
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,490.00	1,110.00	380.00	25.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,915.80	2,103.12	812.68	27.87
+ GST 7.00/7.00% (S\$)	204.11	147.22	56.89	27.87
Nett Amount (S\$)	3,119.91	2,250.34	869.57	27.87

INSPECTION

Date of Assignment: 22/09/2020 Present Location:

ComfortDelGro Engineering Pte Ltd
(Loyang)

Date Inspected: 21/09/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$2,103.11

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2020)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC394C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER	Repair	499.90 FL	-	*- FL
2	1		*FRT BUMPER SIDE BRKT RH	Not Necessary	77.00 FL	-	*- FL
3	1		*FRT FENDER RH	Bent	945.30 FL	-	*945.30 FL
4	1		*FRT FENDER HYBRID RH	Necessary	86.50 FL	-	*86.50 FL
5	1		*FRT WHEEL CAP RH	Cut	177.70 FL	-	*177.70 FL
6	1		*FRT DOOR COMFORTDELGRO RH	Necessary	75.00 F	-	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,861.40	1,284.50
- List Item Discount on L Items 25.00/25.00% (\$)	446.60	302.38
Total Parts (\$)	1,414.80	982.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	480.00
2	SPRAY PAINTING	New	750.00	600.00
3	TUFF KOTE	New	40.00	30.00
Gross Labour Cost (\$\$)			1,490.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >