

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG20010155/EYD3E2**Date:** 08/10/2020**REFERENCE**

Insured/Claimant:	CHONG ZEDONG	Policy No:	2070113862
Date of Loss:	19/09/2020	Nature of Claim:	OD
		Claim No:	7319002621SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU4707D		
Make & Model:	KIA SORENTO, 2.2 (A)	Engine No:	D4HBLH243353
Reg. Date:	14/08/2020 (Man. Year: 2020)	Chassis No:	KNAPH81BSL5650874
Colour:	White	Odometer:	2944 km
Engine Capacity:	2199 cc		
Market Value/New Car Price:	S\$137,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,872.00	3,399.20	4,472.80	56.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	2,270.00	1,880.00	45.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,022.00	5,669.20	6,352.80	52.84
+ GST 7.00/7.00% (S\$)	841.54	396.84	444.70	52.84
Nett Amount (S\$)	12,863.54	6,066.04	6,797.50	52.84

INSPECTION

Date of Assignment:	22/09/2020	
Date Inspected:	22/09/2020 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
2	1		*RR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
3	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
4	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
5	1		*COVER-RR BUMPER, UPR	Dented	605.00 FL	*605.00 FL
6	1		*COVER-RR BUMPER LWR	Cut	565.00 FL	*565.00 FL
7	1		*SKID PLATE-RR BUMPER	Cut	103.00 FL	*103.00 FL
8	1		*WIRING HARNESS - R.P.A.S	Not Necessary	357.00 FL	*- FL
9	1		*RAIL ASSY-REAR BUMPER	Not Necessary	341.00 FL	*- FL
10	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	53.00 FL	*- FL
11	1		*BRACKET-RR BUMPER SIDE LWR, LH	Not Necessary	13.00 FL	*- FL
12	1		*BRACKET-RR BUMPER SIDE LWR, LH	Not Necessary	13.00 FL	*- FL
13	1		*BRACKET ASSY-RR BUMPER SIDE, LH	Not Necessary	25.00 FL	*- FL
14	1		*BRACKET ASSY-RR BUMPER SIDE, RH	Not Necessary	25.00 FL	*- FL
15	1		*COVER-BLANKING RR FOG, LH	Not Necessary	11.00 FL	*- FL
16	1		*COVER-BLANKING RR FOG, RH	Not Necessary	44.00 FL	*- FL
17	1		*LAMP ASSY-REAR FOG & R/REFL, LH	Not Necessary	129.00 FL	*- FL
18	1		*LAMP ASSY-REAR FOG & R/REFL, RH	Not Necessary	129.00 FL	*- FL
19	2		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	374.00 FL	*- FL
20	1		*PANEL ASSY-TAIL GATE	Dented	1,445.00 FL	*1,445.00 FL
21	2		*HINGE ASSY-TAIL GATE	Not Necessary	60.00 FL	*- FL
22	4		*PAD-WINDSHIELD	Not Necessary	68.00 FL	*- FL
23	6		*PAD-WINDSHIELD GLASS	Necessary	12.00 FL	*12.00 FL
24	2		*STOPPER-RR WINDOW GLASS	Not Necessary	8.00 FL	*- FL
25	1		*GROMMET-REAR WIPER	Not Necessary	3.00 FL	*- FL
26	1		*W/STRIP-TAIL GATE OPNG	Not Necessary	128.00 FL	*- FL
27	1		*HANDLE ASSY-TWIN SWING TAIL GA	Not Necessary	88.00 FL	*- FL
28	1		*POWER LATCH ASSY-PWR T/GATE	Not Necessary	652.00 FL	*- FL
29	1		*STRIKER ASSY-T/GATE	Not Necessary	28.00 FL	*- FL
30	2		*LAMP ASSY-LICENSE PLATE	Not Necessary	66.00 FL	*- FL
31	1		*LAMP ASSY-REAR COMB INSIDE, LH	Not Necessary	827.00 FL	*- FL
32	1		*LAMP ASSY-REAR COMB INSIDE, RH	Not Necessary	827.00 FL	*- FL
33	1		*LAMP ASSY-REAR COMBINATION, LH	Not Necessary	493.00 FL	*- FL
34	1		*LAMP ASSY-REAR COMBINATION, RH	Not Necessary	493.00 FL	*- FL
35	1		*MOTOR & LINKAGE ASSY-REAR WPR	Not Necessary	261.00 FL	*- FL
36	1		*LOGO ASSY-KIA SUB	Necessary	69.00 FL	*69.00 FL
37	1		*EMBLEM-SORENTO	Necessary	28.00 FL	*28.00 FL
38	1		*EMBLEM-GT LINE	Necessary	45.00 FL	*45.00 FL
39	1		*MUFFLER ASSY REAR	Bent	1,177.00 FL	*1,177.00 FL
40	1		*CAP RR HOOK	Cut	5.00 FL	*5.00 FL
41	10		*CLIP	Necessary	20.00 FL	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,790.00	4,214.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,918.00	814.80
Total Parts (\$\$)	7,872.00	3,399.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW RR BUMPER & TAILGATE REPAIR RR END PNL	New	2,000.00	800.00
2	RESPRAY RR BUMPER, TAILGATE & RR END PNL	New	1,260.00	700.00
3	REMOVE & REFIT TAILGATE COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, TRIM & CARPET	New	120.00	0.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	REMOVE & REFIT RR WINDSCREEN GLASS	New	240.00	240.00
8	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
9	RENEW REAR EXHAUST SYSTEM	New	200.00	200.00
Gross Labour Cost (S\$)			4,150.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >