KEF: CS/AIG 200101SS/EUd3 ASSIGNMENT Veh No. SM4 47970 From: Date: Estimated Cost: Type M.Ca) / M.Cycle / Bus / Van / Lorry /-Taxi / Prime Mover OD! TP/WS/TP RES/OD RES/EVA/JNV/MV Truck / Traller or KIA Sorento To Inspect Vehicle No: Make: al Workshop m/s Insured / Std / NI / NA . A/C: Colour T/Radlo: Insured / Std / NI / NA Sp.Reading Eng/No: Policy No. C/No: Claims No. Gen. Cond: Good / Fair / Poor / Burnt Sum Insured: Steering: Morder / Jammed / Leaked / Burnt or Excess: (Client's Record) Brake: Ifforder / Jammed / Leaked / Burnt or Make of Veh; Modi: Nil / S/(Rim) / STD A/Rim or Tyre Size: (Policy Condition) Remark: The veh had commenced its N/S BS / DUN / EXNOVA / GY / FS / LIZA (MIC) OHTSU / PIR / SUMI / ·O/S repair at the time of inspection. TOYO / YOKO or Bal. or Market Value: Front Rear Consistent?: Yes or No R/Bal. R/Bal. IDAC Accident Rport: Consistent?: Yes or No L/Bal. UBal. GIA / PR Seen: mm D.O.I. Res.: Yes or No D.O.A. Est. Repairs: days Calliage 3 Val.: Yes or No Survey held at Lum Sum: (Rear I O/S I N/S I U/C I Rooftop or CA I REV I REP. I 24 HRS Vehicle: IN/OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction Date/Time, File Pass to? : Prell. Report Days Of Repair: Survey Fee: Resurvey No. of Trip: : Final Report Transportation: Date/Time, File Return to? Add Fee: : Site Insp (\$ _S + RS,__SI : Interview (\$ Pholos : Tech. Inva (\$ @there Reportionnel: Weel and 15 Lump Sun / LEd: / s TOTAL

٠.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

Steve (LXK)

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte. 2000	Cust No/Name Reg No/Reg Date	LCV12721/Mr Chong Zedong SMU4707D / 14/08/202	
MOTOR CLAIM DEPARTMENT OD- Not Authra	Date In/Mileage		
AIG BUILDING EXMU - "	Engine No	D4HBLH243353	
SINGAPORE 079120 Contact No 64191000 P/P, Ry Befi-	St. Administration (Co.)	KIA/SORENTO 2.2 A D GT SR 4WD GDJI SWP SNOW WHITE PEAR/ WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
AXOOOOO	Credit	22/09/2020/ 12:48	B Bod	442 / CocoLu	N 2002	21405			
LAACCCCC	Credit	Description of Go			Qty	Unit Price	Disc%		ount
		ι L TAILGATE μ19						800 2	000.000
F PNT98000	R END PNL		END DNI 1	J59				700 1	260.00
PNT88000		R , TAILGATE & RR	END PNL ,	03,					120.00
PNT88000		AILGATE COMPONENT	· · ·						120.00
REMOVE & 54900099		R FLR BOARD, TRIM &	CARPET 🏃						30.00
10028901		CTRICAL SYSTEM	G WESCAN PR			<u>7</u>			120.00
USING HI- PNT88000	-SCAN PRO) TEST			<u> </u>	7			240.00
SUNDRY		R WINDSCREEN GLASS							80.0
SUPPLY W	INDSCREEN	N SEALANT						X	50.0
	R NUMBER	PLATE WITH CASING						1	60.0
REMOVE &	REFIT RE	EVERSE SENSOR						12	40.0
SUPPLY CO								20	30.0
Sundries COVER-RR	RUMPER L	IPR / 00			1.00	605.0	0 20.0	0	484.0
COVER-RR	BUMPER L	WR / (U)			1.00		0 20.0		452.
SKID PLAT	TE-RR BUM	IPER / L'ZI			1.00 1.00		00 20.0 00 20.0		82. 285.
WIRING HA					1.00		0 20.0		272.
RAIL ASSI					1.00		00 20.0		42.
ANIENNA A	DO DIMOFO	SIDE LWR, LH ?			1.00		00 20.0		10.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal on added to the course of renewing the rubber seal on added to the course of renewing the rubber seal on added to the course of renewing the rubber seal on added to the course of renewing the rubber seal on added to the course of renewing the rubber seal on the course of renewing the rubber seal of the course of renewing the rubber seal on the course of renewing the rubber seal on the course of renewing the rubber seal of the rubber seal the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
Invoice Name & Address AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12721/Mr Reg No/Reg Date SMU4707D Date In/Mileage / Chassis No KNAPH818SL5 Engine No D4H8LH24335 Make/Model KIA/SORENTO	Chong Zedong / 14/08/202 0 650874		

ccount No Terms Date/Time Printed CSE Operator		WIP No	
4x00000 Credit 22/09/2020/ 12:48 Bod 442 / CocoLu		21405	
Description of Goods / Services	Qty U	nit Price Disc	
7	1.00	13.00 20.	
BRACKET ASSY-RR BUMPER SIDE, LH	1.00	25.00 20.	
BRACKET ASSY-RR BUMPER SIDE, RH	1.00	25.00 20.	
COVER-BLANKING RR FOG, LH	1.00	11.00 20.	
COVER-BLANKING RR FOG, RH X	1.00	44.00 20.	
LAMP ASSY-REAR FOG & R/REFL, LH	1.00	129.00 20.	
LAMP ASSY-REAR FOG & R/REFL,RH X	1.00	129.00 20	
ULTRASONIC SENSOR ASSY-BWS 7	2.00	187.00 20	
PANEL ASSY-TAIL GATE / 00	1.00	1445.00 20	
HINGE ASSY-TAIL GATE X	2.00	30.00 20	
PAD-WINDSHIELD / P/C	-14. 00	17.00 20	
PAD-WINDSHIELD GLASS / 1/4 5 05 1 1000 0	5 8.00	2.00 20	
PAD-WINDSHIELD / NY PAD-WINDSHIELD GLASS / NY STOPPER-RR WINDOW GLASS / NY	2.66	4.00 20	
GROMMET-REAR WIPER INC. CO.	1 4.60-7	3.00 20	2.40
W/STRIP-TAIL GATE OPNG	1.00	128.00 20	
HANDLE ASSY-TWIN SWING TAIL GA	1.00	88.00 20	70.40
POWER LATCH ASSY-PWR T/GATE	1.00	652.00 20	521.60
STRIKER ASSY-T/GATE X	1.00	28.00 20	
	2.00	33.00 20	
LAMP ASSY-LICENSE PLATE X	1.00	827.00 20	
LAMP ASSY-REAR COMB INSIDE, LH	1.00	827.00 20	
LAMP ASSY-REAR COMB INSIDE, RH !	1.00	493.00 20	
LAMP ASSY-REAR COMBINATION, LH X	1.00	493.00 20	*** ***** *** *** *** *** *** *** ***
LAMP ASSY-REAR COMBINATION, RH X	1.00	261.00 20	
MOTOR & LINKAGE ASSY-REAR WPR ≺	1.00	69.00 2	
LOGO ASSY-KIA SUB / MC		28.00 2	
EMBLEM-SORENTO / 1/C	1.00		
EMBLEM-GT LINE / poc	1.00	45.00 2	0.00

Conf	1	2	accepted	by
CONT	11 1	•	accepted	v

LKK Auto Consultants hence notify the Repairer of the following: · To resurvey before/after spray painting To display damaged part(s) during resurvey

10,860.40 Nett 760.23 10860.40 7% GST on

Total Payable

11,620.63

 Parts prices are subject to confirmation · Authorized a ignatory and acompabasis tarp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Perfect of the control of the control of the world many be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a control of the work. Payment for this may be made in cash, credit card or you must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the removal of the windscreen.

Page 2 of 2