



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

Steve (LKK)

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 6 days	Cust No/Name LCV12721/Mr Chong Zedong Reg No/Reg Date SMU4707D / 14/08/202 Date In/Mileage / 0 Chassis No KNAPH81BSL5650874 Engine No D4HBLH243353 Make/Model KIA/SORENTO 2.2 A D GT SR 4WD GDJI Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/09/2020/ 12:48	Bod	442 / CocoLu	21405

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER & TAILGATE REPAIR RR END PNL ?				800 2000.00
E PNT98000 RESPRAY RR BUMPER, TAILGATE & RR END PNL ?				700 1260.00
E PNT88000 REMOVE & REFIT TAILGATE COMPONENT				120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM & CARPET				120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
E PNT88000 REMOVE & REFIT RR WINDSCREEN GLASS				240.00
M SUNDRY SUPPLY WINDSCREEN SEALANT				80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING				NN X 50.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				60.00
M SUNDRY SUPPLY C&C BADGE				40.00
M SUNDRY Sundries				20 30.00
M COVER-RR BUMPER, UPR	1.00	605.00	20.00	484.00
M COVER-RR BUMPER LWR	1.00	565.00	20.00	452.00
M SKID PLATE-RR BUMPER	1.00	103.00	20.00	82.40
M WIRING HARNESS-R.P.A.S	1.00	357.00	20.00	285.60
M RAIL ASSY-REAR BUMPER	1.00	341.00	20.00	272.80
M ANTENNA ASSY-SMARTKEY	1.00	53.00	20.00	42.40
M BRACKET-RR BUMPER SIDE LWR, LH	1.00	13.00	20.00	10.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV12721/Mr Chong Zedong
	Reg No/Reg Date	SMU4707D / 14/08/202
	Date In/Mileage	/ 0
	Chassis No	KNAPH81BSL5650874
	Engine No	D4HBLH243353
	Make/Model	KIA/SORENTO 2.2 A D GT SR 4WD GOJI
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	22/09/2020/ 12:48	Bod	442 / CocoLu	21405
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET-RR BUMPER SIDE LWR,LH		1.00	13.00	20.00	10.40
M BRACKET ASSY-RR BUMPER SIDE,LH		1.00	25.00	20.00	20.00
M BRACKET ASSY-RR BUMPER SIDE,RH		1.00	25.00	20.00	20.00
M COVER-BLANKING RR FOG,LH	X NN	1.00	11.00	20.00	8.80
M COVER-BLANKING RR FOG,RH	X NN	1.00	44.00	20.00	35.20
M LAMP ASSY-REAR FOG & R/REFL,LH	X NN	1.00	129.00	20.00	103.20
M LAMP ASSY-REAR FOG & R/REFL,RH	X NN	1.00	129.00	20.00	103.20
M ULTRASONIC SENSOR ASSY-BWS		2.00	187.00	20.00	299.20
M PANEL ASSY-TAIL GATE	00	1.00	1445.00	20.00	1156.00
M HINGE ASSY-TAIL GATE	X NN	2.00	30.00	20.00	48.00
M PAD-WINDSHIELD	PC	4.00	17.00	20.00	54.40
M PAD-WINDSHIELD GLASS	PC	8.00	2.00	20.00	9.60
M STOPPER-RR WINDOW GLASS	PC	2.00	4.00	20.00	6.40
M GROMMET-REAR WIPER	PC	1.00	3.00	20.00	2.40
M W/STRIP-TAIL GATE OPNG		1.00	128.00	20.00	102.40
M HANDLE ASSY-TWIN SWING TAIL GA	X NN	1.00	88.00	20.00	70.40
M POWER LATCH ASSY-PWR T/GATE		1.00	652.00	20.00	521.60
M STRIKER ASSY-T/GATE	X NN	1.00	28.00	20.00	22.40
M LAMP ASSY-LICENSE PLATE	X NN	2.00	33.00	20.00	52.80
M LAMP ASSY-REAR COMB INSIDE,LH		1.00	827.00	20.00	661.60
M LAMP ASSY-REAR COMB INSIDE,RH		1.00	827.00	20.00	661.60
M LAMP ASSY-REAR COMBINATION,LH	X NN	1.00	493.00	20.00	394.40
M LAMP ASSY-REAR COMBINATION,RH	X NN	1.00	493.00	20.00	394.40
M MOTOR & LINKAGE ASSY-REAR WPR	X NN	1.00	261.00	20.00	208.80
M LOGO ASSY-KIA SUB	PC	1.00	69.00	20.00	55.20
M EMBLEM-SORENTO	PC	1.00	28.00	20.00	22.40
M EMBLEM-GT LINE	PC	1.00	45.00	20.00	36.00

Confirm & accepted by

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Authorized signatory and company stamp

7% GST on Net 10,860.40
10860.40 760.23

Total Payable 11,620.63

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.