

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20010157/GSD3E2  
**Date:** 30/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SGY6775T **Insured Vehicle No :** SKV8554U  
 Date of Loss: 12/09/2020 Nature of Claim: TP Claim No: 8537308014SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY6775T**  
 Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1753226  
 Reg. Date: 04/10/2007 (Man. Year: 2007) Chassis No: RN61047532  
 Colour: Brown Odometer: 115092 km  
 Engine Capacity: 1799 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
 Front Left Side: Lassa 6 mm Rear Left Side: Lassa 6 mm  
 Front Right Side: Lassa 6 mm Rear Right Side: Lassa 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 22/09/2020  
 Date Inspected: 22/09/2020 Inspected At: Hong San Hong Wei Pte Ltd (HQ)  
 Blk 1002 Bukit Merah Lane 3 #01-85  
 Singapore 159719  
 Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Deformed	0.00 F	*- F
3	1		*FRT BUMPER	Cracked	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER BRACKET	Broken	0.00 F	*- F
6	2		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
8	1		*FRT GRILLE	Cracked	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
10	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
11	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
12	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
13	1		*BONNET	Repair	0.00 F	*- F
14	1		*BONNET LOCK	Bent	0.00 F	*- F
15	1		*AIR CON CONDENSER	Cut	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**