

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20010158/GTF3E2
Date: 06/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1700078221
Claimant Vehicle No : SKS9800T	Insured Vehicle No : SLU2116J
Date of Loss: 18/09/2020	Nature of Claim: TP Claim No: 2075305961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS9800T		
Make & Model:	LEXUS GS250, 2.5 Luxury (A)	Engine No:	2ARF208728
Reg. Date:	01/06/2016 (Man. Year: 2016)	Chassis No:	JTHBJ1GG702092516
Colour:	Black	Odometer:	49025 km
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	22/09/2020	
Date Inspected:	23/09/2020 Inspected At:	King's Auto Repair & Service Pte Ltd (HQ) BLK 176 SIN MING DRIVE, #02-10 Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Cracked	0.00 F	*- F
4	1		*REAR BUMPER SPONGE	Deformed	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR	Cut	0.00 F	*- F
6	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
11	1		*REAR EXHAUST CHROME PIPE	Cut	0.00 F	*- F
					Total Parts (S\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >