

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20010159/AEA3Q2**Date:** 11/08/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900162177-01
Claimant Vehicle No :	SKK8029C	Insured Vehicle No :	SMP1284C
Date of Loss:	21/09/2020	Nature of Claim:	TP
		Claim No:	9358017245SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK8029C	Engine No:	CAXA80652
Make & Model:	AUDI A1, 1.4 (A)	Chassis No:	WAUZZZ8X5CB217083
Reg. Date:	30/08/2013 (Man. Year: 2012)	Odometer:	76325 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,157.00	2,969.20	7,187.80	70.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,452.00	3,622.00	3,830.00	51.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,609.00	6,591.20	11,017.80	62.57
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	17,609.00	6,500.00	11,109.00	63.09
+ GST 7.00/7.00% (S\$)	1,232.63	455.00	777.63	63.09
Nett Amount (S\$)	18,841.63	6,955.00	11,886.63	63.09
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,257.00		

INSPECTION

Date of Assignment:	23/09/2020		Premium Automobiles Pte Ltd (HQ)
Date Inspected:	23/09/2020	Inspected At:	55 UBI ROAD 1
			Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$40,000

LTA REBATE: \$33,217

NETT VALUE: \$6,783

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,466.00 FS	*1,172.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT	Torn	165.00 FS	*132.00 FS
4	1		*FRONT SPOILER	Not Necessary	188.00 FS	*- FS
5	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	116.00 FS	*- FS
6	1		*RADIATOR GRILLE	Not Necessary	959.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Damaged	208.00 FS	*166.40 FS
8	1		*FRONT REINFORCEMENT	Not Necessary	684.00 FS	*- FS
9	1		*FRONT FENDER -LH	Dented	878.00 FS	*702.40 FS
10	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	42.00 FS	*- FS
11	1		*FRONT FENDER BRACKET -CENTRE LH	Not Necessary	12.00 FS	*- FS
12	1		*FRONT FENDER BRACKET -LH FRONT	Not Necessary	59.00 FS	*- FS
13	1		*FRONT FENDER BRACE -LH FRONT	Bent	53.00 FS	*42.24 FS
14	1		*FRONT FENDER CLOSING ELEMENT -LH	Not Necessary	25.00 FS	*- FS
15	1		*WHEEL HOUSING LINER	Not Necessary	167.00 FS	*- FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	40.00 FS	*- FS
17	1		*BONNET	Repair	2,235.00 FS	*- FS
18	1		*BONNET ATTACHMENT PARTS	Not Necessary	137.00 FS	*- FS
19	2		*BONNET LID HINGE -LH/RH	Not Necessary	252.00 FS	*- FS
20	2		*BONNET EDGE PROTECTION -FRONT	Not Necessary	40.00 FS	*- FS
21	1		*HEADLIGHT MOUNTING -LH	Not Necessary	103.00 FS	*- FS
22	1		*HALOGEN HEADLIGHT -LH	Cut	924.00 FS	*738.80 FS
23	1		*HALOGEN FOG LAMP	Not Necessary	262.00 FS	*- FS
24	1		*FRONT ALUMINIUM RIM -LH	Repair	587.00 FS	*- FS
25	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
26	1		*SUNDRIES	Necessary	250.00 FS	*15.36 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	10,157.00	2,969.20
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULES	New	700.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER ,BONNET ,LHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,500.00	1,250.00
4	TO RESPRAY FRONT BUMPER ,BONNET ,HINGES AND LHS FRONT FENDER	New	3,500.00	1,650.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,452.00	3,622.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >