

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20010164/T1GS3Q2
Date: 25/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070051428
Claimant Vehicle No :	SH8026G	Insured Vehicle No :	GBH2412R
Date of Loss:	19/09/2020	Nature of Claim:	TP
		Claim No:	5409748709SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8026G		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZR2C10289
Reg. Date:	02/05/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU803080080
Colour:	Blue	Odometer:	166126 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,756.52	3,365.10	391.42	10.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	940.00	110.00	10.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,806.52	4,305.10	501.42	10.43
+ GST 7.00/7.00% (S\$)	336.46	301.36	35.10	10.43

Nett Amount (S\$)	5,142.98	4,606.46	536.52	10.43
+ Loss of Use (2.5 x S\$20.00/day) (S\$)		50.00		
+ Car Rental (2.5 x S\$63.24/day) (S\$)		158.10		
Nett Liability (S\$)		4,814.56		
Global Sum Settlement (S\$)		4,800.00		

INSPECTION

Date of Assignment: 21/09/2020

Date Inspected: 21/09/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FRONT BUMPER	Repair	499.90 FL	*- FL
2	10		*BUMPER PIECE	Not Necessary	22.00 FL	*- FL
3	1		*FENDER SUB-ASSY FRO	Bent	945.30 FL	*945.30 FL
4	1		*EMBLEM SIDE PANEL	Necessary	86.50 FL	*86.50 FL
5	1		*UNIT ASSY HEADLAMP	Cut	3,455.00 FL	*3,455.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	5,008.704,486.80
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,252.181,121.70
					Total Parts (\$\$)	3,756.523,365.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	480.00
2	SPRAYPAINT ON AFFECTED AREA	New	450.00	400.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
Gross Labour Cost (S\$)			1,050.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >