

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20010166/T1SD3E2
Date: 11/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00017272001
Claimant Vehicle No :	FBH7895Y	Insured Vehicle No :	GBJ67G
Date of Loss:	01/09/2020	Nature of Claim:	TP
		Claim No:	SNM20D203190/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH7895Y	Engine No:	5YP206747
Make & Model:	YAMAHA T135, 135cc (A)	Chassis No:	5YP206747
Reg. Date:	09/10/2006 (Man. Year: 2006)	Odometer:	14671 km
Colour:	Dark Blue		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,967.00	1,612.80	2,354.20	59.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	990.00	400.00	590.00	59.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,957.00	2,012.80	2,944.20	59.39
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	4,957.00	1,200.00	3,757.00	75.79

INSPECTION

Date of Assignment:	22/09/2020	
Date Inspected:	23/09/2020	Inspected At: Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3 Singapore 159722
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jan 2021)	
Parts:	N/A	YAMAHA T135 135cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH7895Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*METER ASSY	Not Necessary	190.00 F	*- FL
2	1		*FRONT FORK UNDER BRACKET	Not Necessary	150.00 F	*- FL
3	1		*STEERING CONE BEARING	Necessary	60.00 F	*60.00 FL
4	1		*BODY FRAME ALIGNMENT	Not Necessary	550.00 F	*- FL
5	1		*FRONT FENDER	Cut	60.00 F	*60.00 FL
6	1		*FRONT WHEEL RIM	Not Necessary	180.00 F	*- FL
7	1		*FRONT WHEEL SHALF	Bent	45.00 F	*45.00 FL
8	2		*FRONT WHEEL BEARING	Necessary	40.00 F	*40.00 FL
9	1		*FRONT WHEEL BEARING OIL SEAL	Not Necessary	10.00 F	*- FL
10	1		*FRONT BRAKE DISC	Not Necessary	120.00 F	*- FL
11	1		*HEAD COWLING	Cracked	120.00 F	*120.00 FL
12	1		*PILOT LIGHT	Cut	120.00 F	*120.00 FL
13	1		*STATER SWITCH RH	Cracked	60.00 F	*60.00 FL
14	1		*SIGNAL SWITCH LH	Cracked	120.00 F	*120.00 FL
15	1		*HANDLE BAR	Bent	90.00 F	*90.00 FL
16	1		*HANDLE BAR GRIP	Torn	15.00 F	*15.00 FL
17	1		*HANDLE BAR BALANCER	Missing	50.00 F	*50.00 FL
18	1		*HANDLE BAR FRONT COVER	Cracked	80.00 F	*80.00 FL
19	1		*HANDLE BAR REAR COVER	Cracked	80.00 F	*80.00 FL
20	1		*FRONT NO PLATE	Bent	12.00 F	*12.00 FL
21	1		*BRAKE LEVER	Cut	25.00 F	*25.00 FL
22	1		*CLUTCH LEVER	Cut	25.00 F	*25.00 FL
23	1		*SIDE MIRROR	Missing	40.00 F	*40.00 FL
24	1		*HEADLIGHT	Cracked	120.00 F	*120.00 FL
25	1		*HANDLE BAR BRACKET	Bent	80.00 F	*80.00 FL
26	1		*CLUTCH CABLE	Not Necessary	35.00 F	*- FL
27	1		*CHOKE CABLE	Not Necessary	30.00 F	*- FL
28	1		*THOTRO CABLE	Not Necessary	80.00 F	*- FL
29	1		*GEAR PEDAL	Bent	60.00 F	*60.00 FL
30	1		*BRAKE PEDAL	Not Necessary	60.00 F	*- FL
31	1		*FRONT FOOT REST RUBBER	Torn	30.00 F	*30.00 FL
32	1		*FRONT FOOT REST BRACKET	Bent	80.00 F	*80.00 FL
33	1		*EXHAUST + GASKET	Repair	280.00 F	*- FL
34	1		*EXHAUST COVER	Cut	80.00 F	*80.00 FL
35	1		*TAILBOARD LH / RH	N/S Repair / O/S Cut	180.00 F	*90.00 FL
36	1		*TOP BOX	Not Necessary	150.00 F	*- FL
37	1		*TOP BOX BRACKET	Not Necessary	70.00 F	*- FL
38	1		*REAR FOOT REST	Cut	50.00 F	*50.00 FL
39	1		*HP BRACKET	Bent	45.00 F	*45.00 FL
40	1		*IU UNIT	Not Necessary	180.00 F	*- FL
41	1		*IU UNIT BRACKET	Bent	35.00 F	*35.00 FL
42	1		*SIGNAL RELAY	Distorted	25.00 F	*25.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*HANDLE BRACKET	Bent	55.00 F	*55.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					3,967.00	1,792.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	179.20
Total Parts (\$\$)					3,967.00	1,612.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	FORK ALIGNMENT	New	280.00	120.00
2	LABOUR	New	680.00	250.00
3	TOWING	New	30.00	30.00
Gross Labour Cost (\$\$)			990.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >