

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20010167/AGS3Q2

Date:

17/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800116184

Claimant Vehicle No : SJY1236E**Insured Vehicle No :**

SBL1230J

Date of Loss: 18/09/2020

Nature of Claim:

TP

Claim No:

2654994339SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJY1236E**

Make & Model: MITSUBISHI LANCER, 1.5 (A)

Engine No: 4A910144910

Reg. Date: 03/08/2010 (Man. Year: 2010)

Chassis No: JMYSRCY2AAU001640

Colour: White

Odometer: 126460 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Davanti 6 mm

Rear Left Side: Davanti 6 mm

Front Right Side: Davanti 6 mm

Rear Right Side: Davanti 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,942.50	4,463.70	4,478.80	50.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	2,780.00	1,520.00	35.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,242.50	7,243.70	5,998.80	45.30
Approved Total (Overridden) (S\$)		5,800.00		

Nett Amount (S\$)	13,242.50	5,800.00	7,442.50	56.20
+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)		1,070.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,906.45		

INSPECTION

Date of Assignment: 22/09/2020

Date Inspected: 23/09/2020

Estimated Period of Repair: 7.0 days

Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
 Singapore 417807

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	794.00 FL	*794.00 FL
2	2		*REAR BOOTLID HINGE LH & RH	Not Necessary	150.00 FL	*- FL
3	1		*REAR BOOTLID LANCER EMBLEM	Necessary	45.00 FL	*45.00 FL
4	1		*REAR BOOTLID GX EMBLEM	Necessary	48.00 FL	*48.00 FL
5	1		*REAR BOOTLID MRK THREE DIA	Necessary	42.00 FL	*42.00 FL
6	1		*REAR BOOTLID TOP LOCK	Damaged	98.00 FL	*98.00 FL
7	1		*REAR BOOTLID LOWER LOCK	Not Necessary	57.00 FL	*- FL
8	2		*REAR BOOTLID STOPPER LH & RH	Not Necessary	36.00 FL	*- FL
9	1		*REAR BOOTLID WEATHERSTRIP	Cut	186.00 FL	*186.00 FL
10	2		*REAR BOOTLIDLAMP LH & RH	Not Necessary	348.00 FL	*- FL
11	1		*REAR BOOTLID REFLECTOR	Not Necessary	348.00 FL	*- FL
12	1		*REAR BUMPER	Distorted	747.00 FL	*747.00 FL
13	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	70.00 FL	*70.00 FL
14	1		*REAR BUMPER CENTRE BEAM	Bent	273.00 FL	*273.00 FL
15	2		*REAR TAILLAMP LH & RH	Cracked	790.00 FL	*790.00 FL
16	2		*REAR TAILLAMP PANEL LH	Repair	145.00 FL	*- FL
17	2		*REAR FENDER LH	Repair	895.00 FL	*- FL
18	2		*REAR FENDER INNER COWLING LH & RH	Not Necessary	390.00 FL	*- FL
19	2		*REAR FENDER AIR VENT LH & RH	Not Necessary	176.00 FL	*- FL
20	2		*REAR FENDER INNER TRIM LH & RH	Torn	508.00 FL	*508.00 FL
21	1		*REAR END PANEL	Dented	545.00 FL	*545.00 FL
22	1		*REAR END PANEL TOP GARNISH	Deformed	144.00 FL	*144.00 FL
23	1		*REAR SPARE TYRE PANEL	Repair	776.00 FL	*- FL
24	1		*REAR SPARE TYRE PANEL TOP BOARD	Torn	187.00 FL	*187.00 FL
25	1		*REAR SPARE TYRE PANEL BOLT	Not Necessary	35.00 FL	*- FL
26	1		*REAR ANTENAR KEYLESS	Not Necessary	142.00 FL	*- FL
27	1		*REAR DOOR LH	Not Necessary	934.00 FL	*- FL
28	1		*REAR NUMBER PLATE LAMP	Cracked	78.00 FL	*78.00 FL
29	1		*REAR BUMPER REFLECTOR	Cracked	138.00 FL	*138.00 FL
30	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
31	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
32	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*10.00 FS
34	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	70.00 FS	*- FS
35	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					9,855.00	4,933.00
- List Item Discount on L Items 10.00/10.00% (\$)					912.50	469.30
Total Parts (\$)					8,942.50	4,463.70
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND PANEL BEAT THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	1,200.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	1,300.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	60.00
5	TO REMOVE & REPLACE REVERSE SENSOR AND CHECK FOR PROPER FUNCTIONS	New	120.00	50.00
6	TO REMOVE & REFIX /REPLACE REAR TRIMS ,GARNISH AND FITTINGS SO AS TO FACILITATE REPIARS AS REAR COMARTMENT	New	180.00	80.00
7	TO CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
8	TO TRANSFER REAR BOOT MECHANISM	New	150.00	60.00
Gross Labour Cost (\$)			4,300.00	2,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >