

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 29.09.20

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SJJ2697E
MODEL : HONDA FIT
DATE OF ACCIDENT : 19.09.20
TIME OF ACCIDENT : 12:20HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 849.90	\$ 849.90
2	TAIL GATE OUTER GARNISH <i>let</i>	1	\$ 236.80	\$ 236.80
3	TAIL GATE NUMBER PLATE LAMP <i>new</i>	2	\$ 45.00	\$ 90.00
4	TAIL GATE LOGO <i>new</i>	1	\$ 24.70	\$ 24.70
5	TAIL GATE WIPER ARM <i>2</i>	1	\$ 69.80	\$ 69.80
6	TAIL GATE WIPER ARM BOLT COVER <i>new</i>	1	\$ 42.10	\$ 42.10
7	TAIL GATE WIPER MOTOR	1	\$ 436.30	\$ 436.30
8	TAIL GATE OUTER LOCK HANDLE	1	\$ 89.60	\$ 89.60
9	TAIL GATE HINGE <i>new</i>	2	\$ 42.00	\$ 84.00
10	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 47.10	\$ 47.10
11	TAIL GATE STOPPER <i>new</i>	2	\$ 12.00	\$ 24.00
12	TAIL GATE INNER LOCK <i>new</i>	1	\$ 169.40	\$ 169.40
13	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 25.00	\$ 25.00
14	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 134.50	\$ 134.50
15	TAIL GATE INNER TRIM <i>new</i>	1	\$ 372.20	\$ 372.20
16	TAIL GATE WINDSCREEN MOULDING <i>new</i>	2	\$ 76.00	\$ 152.00
17	TAIL LAMP <i>2x new</i>	2	\$ 296.10	\$ 592.20
18	REAR FENDER INNER COWLING <i>new</i>	2	\$ 78.10	\$ 156.20
19	REAR FENDER INNER TRIM <i>new</i>	2	\$ 298.90	\$ 597.80
20	REAR END PANEL <i>Dented</i>	1	\$ 356.70	\$ 356.70
21	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 116.20	\$ 116.20
22	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 185.60	\$ 185.60
23	REAR TOOLS BOX <i>Dented</i>	1	\$ 294.20	\$ 294.20

TOTAL PRICE \$ 5,146.30
LESS 20% \$ 1,029.26
SUB TOTAL PRICE \$ 4,117.04

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJJ2697E
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 19.09.20
 TIME OF ACCIDENT : 12:20HRS

2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
3	REAR BUMPER DIFFUSER (SPECIAL TYPE) <i>del d</i>	1	\$ 1,800.00	\$ 1,800.00	1200(S20)
4	TAIL GATE OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	20
5	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	60
6	TAILGATE INNER TRIM SEAL (SPECIAL TYPE) <i>new</i>	1	\$ 80.00	\$ 80.00	+
7	TAIL GATE WINDSCREEN SEALANT <i>3 per</i>	1	\$ 80.00	\$ 80.00	40
8	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
9	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	10
10	REAR FENDER INNER COWLING (SET) <i>3 per</i>	1	\$ 60.00	\$ 60.00	+
11	REAR FENDER INNER TRIM CLIPS (SET) <i>3 per</i>	1	\$ 80.00	\$ 80.00	+
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
13	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
14	REVERSE SENSOR <i>2 per</i>	1	\$ 220.00	\$ 220.00	200
15	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	+

1660

TOTAL \$ 3,320.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
10	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SJJ2697E
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 19.09.20
 TIME OF ACCIDENT : 12:20HRS

11	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

2100

TOTAL \$4,280.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,437.04
 TOTAL LABOUR COST : \$ 4,280.00
 TOTAL REPAIR COST : \$ 11,717.04

Adrian Li
 r/s 30/09/20
 06 days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

total: 5592.80
 4/5: 4.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: