Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20010169/AGQF3Q2

Date: 09/11/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001293206 Claimant SJK4666B **Insured Vehicle No: GBA9628B** Vehicle No:

Date of Loss: 14/09/2020 Nature of Claim: TP Claim No: 247560

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJK4666B Reg No:

Make & Model: HONDA CIVIC, 1.6 5AT (A) Engine No: R16A14000265 Chassis No: Reg. Date: 22/10/2008 (Man. Year: 2008) JHMFD46209S200028 147422 km

Colour: Odometer: Silver

Engine Capacity: 1595 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: ACENDA 6 mm Rear Left Side: ACENDA 6 mm Front Right Side: Rear Right Side: ACENDA 6 mm ACENDA 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,226.40	698.16	528.24	43.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	400.00	450.00	52.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,076.40	1,098.16	978.24	47.11
Approved Total (Overridden) (S\$)		850.00		
(S\$)	2,076.40	850.00	1,226.40	59.06
+ GST 7.00/7.00% (S\$)	145.35	59.50	85.85	59.06
Nett Amount (S\$)	2,221.75	909.50	1,312.25	59.06

INSPECTION

Date of Assignment: 22/09/2020

Date Inspected: 29/09/2020 Inspected At: People's Vehicle Recovery Service

Blk 3023A Ubi Rd 1, #01-60

Singapore 408717

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Nov 2020)

Parts: 143 HONDA CIVIC 1.6 5AT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJK4666B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BUMPER FRT	Deformed	668.00 FL	*668.00 FL	
2	1		*BUMPERSIDE RETAINER L/H FRT	Necessary	85.00 FL	*24.00 FL	
3	1		*BUMPER REINFORCEMENT FRT	Not Necessary	248.60 FL	*-FL	
4	1		*NUMBER PLATE GARNISH FRT	Deformed	118.20 FL	*118.20 FL	
5	1		*GRILLE	Not Necessary	228.60 FL	*-FL	
6	1		*GRILLE LOGO	Not Necessary	35.60 FL	*- FL	
7	1		*NUMBER PLATE AND BASE FRT	Bent	50.00 FS	*50.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
				Sub Total (S\$)	1,434.00	860.20	
	- List Item Discount on L Items 15.00/20.00% (S\$)_		207.60	162.04			
				Total Parts (S\$)_	1,226.40	698.16	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	400.00	200.00
2	SPRAY PAINTING ACCIDENT EFFECT PARTS	New	450.00	200.00
	Gross Labour Cost (S\$)		850.00	400.00
	Report was unsubmitted du	uring this print-out.		

< END OF ESTIMATES >