

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20010171/KRS3Q2**Date:** 03/02/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900155319
Claimant
Vehicle No : SKQ4570A **Insured Vehicle No :** SMN8943Z
Date of Loss: 21/09/2020 Nature of Claim: TP Claim No: 3830419841SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ4570A**
Make & Model: VOLKSWAGEN SHARAN, 2.0 TSI 7N24MY (A) Engine No: DED033917
Reg. Date: 16/04/2019 (Man. Year: 2018) Chassis No: WVVZZZ7NZKV006781
Colour: Metallic Light Brown Odometer: 27811 km
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,229.80	2,300.00	2,929.80	56.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,140.00	1,870.00	62.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,239.80	3,440.00	4,799.80	58.25
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	8,239.80	2,550.00	5,689.80	69.05
+ GST 7.00/7.00% (S\$)	576.79	178.50	398.29	69.05
Nett Amount (S\$)	8,816.59	2,728.50	6,088.09	69.05
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Car Rental (2.0 x S\$180.00/day + 7.00% GST) (S\$)		385.20		
(S\$)		3,413.70		
Liabie Amount (80.00%) (S\$)		2,730.96		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,732.96		
Global Sum Settlement (S\$)		2,650.00		

INSPECTION

Date of Assignment: 22/09/2020
Date Inspected: 02/11/2020 Inspected At:

Kgc Workshop Pte Ltd (AMK)
14 Ang Mo Kio Street 63, Blk B
Singapore 569116

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RHS	Bent	1,450.00 FL	*1,450.00 FL
2	1		*REAR FENDER INNER SHIELD RHS	Serviceable	220.00 FL	*- FL
3	1		*REAR BUMPER	Buckled	1,050.00 FL	*1,050.00 FL
4	1		*REAR BUMPER RETAINER	Serviceable	52.00 FL	*- FL
5	1		*REAR REFLECTOR RHS	Serviceable	65.00 FL	*- FL
6	1		*REAR LOWER ARM RHS	Serviceable	385.00 FL	*- FL
7	1		*REAR SHOCK ABSORBER RHS	Serviceable	375.00 FL	*- FL
8	1		*REAR KNUCKLE ARM ,BEARING ,HUB RHS	Serviceable	625.00 FL	*- FL
9	1		*SET RHS FENDER CLIPS	Not Necessary	50.00 FS	*- FS
10	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
11	1		*RHS REAR RIM	Serviceable	800.00 FS	*- FS
12	1		*RHS REAR TYRE	Serviceable	150.00 FS	*- FS
13	1		*SET REVERSE SENSOR	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,652.00	2,550.00
- List Item Discount on L Items 10.00/10.00% (\$)	422.20	250.00
Total Parts (\$)	5,229.80	2,300.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS	New	1,200.00	600.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	1,200.00	440.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
4	TO PERFORM WHEEL ALIGNMENT	New	80.00	0.00
5	TO REMOVE AND REFIT UNDERCARRIAGE TO FACILITATE REPAIR	New	300.00	0.00
6	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	100.00	20.00
7	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	30.00
Gross Labour Cost (S\$)			3,010.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >