



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBA 7100U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FAIRING	CRACKED	125.00	125.00
1	REAR RIM	NOT NECESSARY	95.00	-
1	REAR TYRE	NOT NECESSARY	70.00	-
1	REAR NUMBER PLATE HOLDER	CUT	25.00	25.00
1	REAR TAILLAMP	CRACKED	175.00	95.00
1	REAR TAILLAMP GARNISH	CRACKED	85.00	85.00
1	REAR TAILLAMP SIDE GARNISH	CRACKED	115.00	115.00
1	LEFT HANDLE HOLDER	DAMAGED	40.00	40.00
1	SET REAR SIDE MIRROR	NOT NECESSARY	100.00	-
1	FRONT BRAKE LEVER (LH)	CUT	75.00	75.00
1	SIDE STAND (LH)	CUT	55.00	55.00
	LESS 10% DISCOUNT		-	-61.50
			960.00	553.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00
			30.00	30.00
	<u>LABOUR</u>			
	TO SUPPLY LABOUR TO REPLACE ABOVE MENTIONED PARTS.		450.00	200.00
	TO SUPPLY LABOUR & PAINT TO SPRAY ACCIDENT AFFECTED AREA.		550.00	200.00
	TO SUPPLY LABOUR TO REWIRE THE REPLACE PARTS.		60.00	20.00
			1,060.00	420.00
GRAND TOTAL			2,050.00	1,003.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				500.00

Report Ref No. CS/LPC20010173/Atd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.