

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20010183/T1EA3Q2
Date: 16/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800104487
Claimant Vehicle No :	GBH5028Y	Insured Vehicle No :	GBH7169K
Date of Loss:	21/09/2020	Nature of Claim:	TP
		Claim No:	3487544863SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH5028Y		
Make & Model:	NISSAN NV200, 1.5 (M)	Engine No:	K9KE628D415608
Reg. Date:	20/06/2018 (Man. Year: 2018)	Chassis No:	VSKYBAM20Z0156303
Colour:	Silver	Odometer:	63940 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Grenlander 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,241.16	3,742.37	2,498.79	40.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,890.00	1,580.00	45.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,711.16	5,632.37	4,078.79	42.00
+ GST 7.00/7.00% (S\$)	679.78	394.27	285.51	42.00

Nett Amount (S\$)	10,390.94	6,026.64	4,364.30	42.00
+ Loss of Use (7.0 x S\$90.00/day) (S\$)		630.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,658.64		

INSPECTION

Date of Assignment: 23/09/2020

Date Inspected: 23/09/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Woon Meng Motor Pte Ltd (Bukit Batok)
 50 Bukit Batok Street 23,, #01-06 Midview Building
 Singapore 659578

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE N/S	Bent	1,336.00 FN	*1,336.00 FN
2	1		*REAR TAILGATE LOCK N/S	Not Necessary	138.00 FN	*- FN
3	2		*REAR TAILGATE HINGE N/S	Repair	210.00 FN	*- FN
4	1		*REAR TAILGATE INNER TRIM N/S	Not Necessary	342.00 FN	*- FN
5	1		*NV200	Necessary	88.00 FN	*88.00 FN
6	1		*EMBLEM	Necessary	145.60 FN	*145.60 FN
7	1		*REAR TAILGATE O/S	Bent	1,504.90 FN	*1,053.70 FN
8	1		*REAR TAILGATE LOCK O/S	Not Necessary	138.00 FN	*- FN
9	2		*REAR TAILGATE HINGE O/S	Repair	210.00 FN	*- FN
10	1		*REAR TAILGATE INNER TRIM O/S	Not Necessary	342.00 FN	*- FN
11	1		*REAR BUMPER	Deformed	700.80 FN	*700.80 FN
12	2		*REAR BUMPER RETAINER	Necessary	82.00 FN	*82.00 FN
13	1		*REAR BUMPER SPONGE	Deformed	145.20 FN	*145.20 FN
14	1		*REAR END PANEL INNER	Repair	485.40 FN	*- FN
15	1		*REAR END PANEL OUTER	Bent	268.00 FN	*268.00 FN
16	1		*REAR END PANEL TOP GARNISH	Not Necessary	165.50 FN	*- FN
17	1		*REAR RUBBER	Not Necessary	105.00 FN	*- FN
18	2		*REAR BUMPER REFLECTOR	Not Necessary	156.00 FN	*- FN
19	10		*CLIPS	Necessary	40.00 FS	*30.00 FS
20	1		*SET REAR SENSOR	Necessary	220.00 FS	*200.00 FS
21	1		*70KM	Necessary	15.00 FS	*15.00 FS
22	3		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	6,897.40	4,124.30
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	656.24	381.93
Total Parts (\$\$)	6,241.16	3,742.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & REPLACE & INSTALL FRONT DAMAGED PARTS	New	1,500.00	700.00
2	TO R&R REAR WINDSCREEN GLASS /N/S /O/S	New	250.00	180.00
3	TO R&R LIGHT WIRING	New	60.00	30.00
4	TO R&R SENSOR WIRING	New	80.00	30.00
5	TO PUTTY & SPRAY PAINTING	New	1,200.00	700.00
6	TO NUMBERING COMPANY LOGO	New	380.00	250.00
Gross Labour Cost (\$\$)			3,470.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >