

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010184/ATD3E2

Date: 25/03/2021

REFERENCE

Insured/Claimant: YIP CHEEN PHANG(YE ZHANPENG) Policy No: 2100440289
Date of Loss: 17/09/2020 Nature of Claim: OD Claim No: 7793730443SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK7751G**
Make & Model: AUDI A4, 1.8 T FSI MU S-Line CVT ABS (A) Engine No: CJE115111
Reg. Date: 28/11/2015 (Man. Year: 2015) Chassis No: WAUZZZ8K4FA183961
Colour: Black Odometer: 138546 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,558.00	4,712.80	6,845.20	59.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,114.00	3,014.00	3,100.00	50.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,672.00	7,726.80	9,945.20	56.28
+ GST 7.00/7.00% (S\$)	1,237.04	540.88	696.16	56.28
Nett Amount (S\$)	18,909.04	8,267.68	10,641.36	56.28

INSPECTION

Date of Assignment: 23/09/2020

Date Inspected: 22/09/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,278.00 F	*1,822.40 F
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	256.00 F	*- F
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	225.00 F	*- F
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	134.00 F	*- F
5	1		*FRONT BUMPER SUPPORT ELEMENT- UPPER CENTRE	Not Necessary	192.00 F	*- F
6	1		*FRONT BUMPER SUPPORT ELEMENT - UPPER	Not Necessary	59.00 F	*- F
7	1		*RADIATOR GRILLE	Not Necessary	1,077.00 F	*- F
8	1		*FRONT BUMPER VENT GRILLE - RH	Not Necessary	134.00 F	*- F
9	1		*FRONT WHEEL SPOILER - RH	Not Necessary	51.00 F	*- F
10	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 F	*- F
11	1		*FRONT FENDER - RH	Dented	979.00 F	*782.80 F
12	1		*FRONTFENDER ATTACHEMENTS PARTS	Not Necessary	57.00 F	*- F
13	1		*FRONT FENDER BRACKET - RH	Not Necessary	52.00 F	*- F
14	1		*DEFORMATION ELEMENT BRACKET - RH REAR	Not Necessary	49.00 F	*- F
15	1		*FRONT FENDER BRACE - RH LOWER	Bent	117.00 F	*93.60 F
16	1		*WHEEL HOUSING LINER	Not Necessary	237.00 F	*- F
17	1		*WHEEL HOUSING LINER ATTACHEMENT PARTS	Not Necessary	44.00 F	*- F
18	1		*STONE CHIP GUARD	Necessary	72.00 F	*57.36 F
19	1		*ADHESIVE TAPE	Not Necessary	54.00 F	*- F
20	1		*HEADLIGHT MOUNTING - RH	Cracked	117.00 F	*93.60 F
21	1		*HEADLIGHT BRACKET - RH	Not Necessary	105.00 F	*- F
22	1		*HEADLIGHT - RH	Cracked	2,316.00 F	*1,852.80 F
23	1		*GAS DISCHARGE LAMP	Not Necessary	408.00 F	*- F
24	1		*DAY DRIVING LIGHTS POWER MODULE	Not Necessary	538.00 F	*- F
25	1		*GAS DISCHARGE LAMP CONTROL UNIT	Not Necessary	1,084.00 F	*- F
26	1		*RETAINING PLATE - RH	Not Necessary	24.00 F	*- F
27	1		*HEADLIGHT HOSE - RH	Not Necessary	36.00 F	*- F
28	1		*HALOGEN FOG LAMP - RH	Not Necessary	259.00 F	*- F
29	1		*LIFT CYLINDER	Not Necessary	208.00 F	*- F
30	1		*FRONT NO PLATE	Not Necessary	60.00 F	*- F
31	1		*SUNDRIES	Necessary	300.00 F	*10.24 F
					Total Parts (\$\$)	11,558.00 4,712.80

F=Franchise part.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECH AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND OWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	3,000.00	1,100.00
5	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			6,114.00	3,014.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >