

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20010185/AGQF3E2
Date: 15/10/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29138602AVW
Claimant Vehicle No : SLB4026Y	Insured Vehicle No :	SMQ5688P
Date of Loss: 19/09/2020	Nature of Claim:	TP
		Claim No: 628889

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB4026Y	Engine No:	LEB4228539
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71015219
Reg. Date:	06/04/2016 (Man. Year: 2015)	Odometer:	107158 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Rovelo 6 mm	Rear Left Side:	Rovelo 6 mm
Front Right Side:	Rovelo 6 mm	Rear Right Side:	Rovelo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,951.20	5,314.96	2,636.24	33.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	2,030.00	720.00	26.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,701.20	7,344.96	3,356.24	31.36
Approved Total (Overridden) (S\$)		5,850.00		
Nett Amount (S\$)	10,701.20	5,850.00	4,851.20	45.33

INSPECTION

Date of Assignment:	22/09/2020	
Date Inspected:	23/09/2020 Inspected At:	Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit) Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Oct 2020)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB4026Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	1,293.00 FL	*1,193.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	175.00 FL	*175.00 FL
3	1		*REAR TAILGATE LOGO EMBLEM	Necessary	76.00 FL	*76.00 FL
4	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	78.00 FL	*78.00 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	85.80 FL	*85.80 FL
6	2		*REAR TAILGATE NO PLATE LAMP L/R	Not Necessary	104.80 FL	*- FL
7	1		*REAR TAILGATE NO PLATE LAMP GARNISH	Not Necessary	243.00 FL	*- FL
8	1		*REAR TAILGATE NO PLATE TOP CHROME	Not Necessary	480.00 FL	*- FL
9	2		*REAR TAILGATE HINGE L/R	Not Necessary	133.20 FL	*- FL
10	2		*REAR TAILGATE DAMPER L/R	Not Necessary	330.00 FL	*- FL
11	1		*REAR TAILGATE STOPPER RH	Not Necessary	25.00 FL	*- FL
12	1		*REAR TAILGATE WEATHER STRIP	Cut	185.60 FL	*185.60 FL
13	1		*REAR TAILGATE MECHANISM LOCK	Damaged	397.90 FL	*187.50 FL
14	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	39.00 FL	*- FL
15	1		*REAR TAILGATE INNER TRIM	Cracked	435.80 FL	*435.80 FL
16	1		*REAR TAILGATE INNER TRIM HANDLE	Not Necessary	56.10 FL	*- FL
17	1		*REAR TAILLAMP RH	Cracked	520.50 FL	*520.50 FL
18	1		*REAR TAILLAMP PANEL (OUTER)	Repair	255.00 FL	*- FL
19	1		*REAR BUMPER	Distorted	1,080.60 FL	*1,080.60 FL
20	1		*REAR BUMPER SIDE REFLECTOR GARNISH RH	Deformed	109.80 FL	*109.80 FL
21	1		*REAR BUMPER SIDE REFLECTOR RH	Cracked	86.40 FL	*86.40 FL
22	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	90.80 FL	*90.80 FL
23	1		*REAR BUMPER TOWING COVER	Deformed	48.00 FL	*48.00 FL
24	1		*REAR END PANEL	Dented	695.00 FL	*560.80 FL
25	1		*REAR END PANEL GARNISH	Deformed	205.80 FL	*205.80 FL
26	1		*REAR SPARE TYRE PANEL TOP BOARD	Deformed	305.80 FL	*305.80 FL
27	1		*REAR SPARE TYRE PANEL TOP TRAY	Cracked	266.40 FL	*266.40 FL
28	1		*REAR FENDER INNER TRIM BOARD RH	Cracked	849.20 FL	*489.60 FL
29	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
30	1		*REAR TAILGATE REVERSE CAMERA	Not Necessary	400.00 FS	*- FS
31	1		*REAR NO PLATE	Not Necessary	30.00 FS	*- FS
32	1		*REAR NO PLATE GARNISH	Not Necessary	50.00 FS	*- FS
33	1		*REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
34	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
35	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
36	1		*REAR END PANEL GARNISH CLIP	Necessary	30.00 FS	*30.00 FS
37	1		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 9,681.50 6,551.20

- List Item Discount on L Items 20.00/20.00% (\$\$) 1,730.30 1,236.24

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (\$)	7,951.20	5,314.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RECTIFY ELECTRICAL FAULTS WHERE NECESSARY	New	60.00	30.00
2	TO TRANSFER TAILGATE MECHANISM AND WIRING ASSY	New	60.00	60.00
3	TO REMOVE, REFIX REAR TAILGATE WINDSCREEN	New	150.00	120.00
4	TO REMOVE AND REPLACE AND REINSTALL REAR REVERSE SENSOR	New	120.00	50.00
5	TO REMOVE & REFIX REVERSE CAMERA ASSY	New	100.00	50.00
6	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS	New	160.00	60.00
7	TO RUSTPROOF AFFECTED AREAS	New	100.00	60.00
8	TO STRAIGHTEN, REPAIR, REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	800.00
9	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	800.00
			Gross Labour Cost (S\$)	2,750.00
				2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >