

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 13 Oct 2020

Preliminary Advice

Insured Vehicle No	: SMQ5688P	Accident Date	: 19/09/2020
TP Vehicle No	: SLB4026Y	Assignment Date	: 22/09/2020
Make	: HONDA SHUTTLE HYBRID	Est. Duration of Repair	: 6
Date of Inspection	: 23/09/2020		
Inspection At	: SIN YU SIN WORKSHOP (HQ) 1 KAKI BUKIT AVE 6 #01-52 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,701.20
Revised Amount	:S\$	7,344.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,344.88
 Lump Sum Repair	 :S\$	 5,850.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- The vehicle is economical for repair
 The vehicle is not economical for repair
 Part-by-Part repair
 Lump Sum repair

 The above survey was conducted on a 'without prejudice' basis.