



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 323Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOOTLID	DENTED	1,980.00	1,980.00
1	REAR BOOTLID EMBLEM (LOGO)	NECESSARY	117.00	117.00
1	REAR BOOTLID EMBLEM (730)	NECESSARY	144.00	144.00
1	REAR BOOTLID CHROME	CUT	234.00	234.00
1	REAR LAMP ASSY	CRACKED	990.00	800.00
	LESS 10% DISCOUNT		-346.50	-327.50
			3,118.50	2,947.50
	<b><u>LABOUR</u></b>			
	SPRAY PAINTING.		600.00	500.00
	TO TRANSFER TAILGATE ACCESSORIES.		100.00	50.00
	TO RENEW ABOVE PARTS.		700.00	300.00
	TO CHECK WIRING AND ERASE ALL CODE.		50.00	30.00
			1,450.00	880.00
<b>GRAND TOTAL</b>			<b>4,568.50</b>	<b>3,827.50</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,827.50</b>

Report Ref No. CS/LPC20010189/Gsd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.