

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20010194/KTD3Q2

Date: 12/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070110055

Claimant
Vehicle No : SMG8091T **Insured Vehicle No :** SMU4399J

Date of Loss: 19/09/2020 Nature of Claim: TP Claim No: 5541840305SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG8091T		
Make & Model:	TOYOTA WISH, 1.8 X (A)	Engine No:	2ZR0432989
Reg. Date:	14/08/2009 (Man. Year: 2009)	Chassis No:	ZGE200011057
Colour:	Metallic Silver	Odometer:	180381 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Firenza 8 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Firenza 8 mm	Rear Right Side:	Firenza 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,521.35	6,457.21	10,064.14	60.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,210.00	2,380.00	2,830.00	54.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,731.35	8,837.21	12,894.14	59.33
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	21,731.35	7,000.00	14,731.35	67.79
+ GST 7.00/7.00% (S\$)	1,521.19	490.00	1,031.19	67.79
Nett Amount (S\$)	23,252.54	7,490.00	15,762.54	67.79

INSPECTION

Date of Assignment: 23/09/2020

Date Inspected: 23/09/2020 Inspected At: Yee Auto Pte Ltd (HQ)
160 SIN MING DRIVE, #02-17 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	950.50 F	*566.00 FL
2	1		*REAR BUMPER BRACKET-LH	Distorted	105.20 F	*105.20 FL
3	1		*REAR BUMPER BRACKET-RH	Distorted	105.20 F	*105.20 FL
4	1		*REAR BUMPER SIDE RETAINER-LH	Serviceable	77.80 F	*- FL
5	1		*REAR BUMPER SIDE RETAINER-RH	Distorted	77.80 F	*77.80 FL
6	1		*REAR BUMPER REFLECTOR-LH	Serviceable	67.10 F	*- FL
7	1		*REAR BUMPER REFLECTOR-RH	Cracked	67.10 F	*67.10 FL
8	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
9	1		*REAR END PANEL	Bent	560.94 F	*560.94 FL
10	1		*REAR END PANEL TOP GARNISH	Buckled	288.90 F	*288.90 FL
11	1		*REAR END PANEL LOWER GARNISH	Serviceable	288.90 F	*- FL
12	1		*TAIL LAMP LH	Cut	526.20 F	*408.00 FL
13	1		*TAIL LAMP RH	Cut	526.20 F	*408.00 FL
14	1		*REAR NUMBER PLATE LAMP-LH	Serviceable	102.40 F	*- FL
15	1		*REAR NUMBER PLATE LAMP-RH	Serviceable	102.40 F	*- FL
16	1		*REAR WINDSCREEN MOULDING	Necessary	134.41 F	*134.41 FL
17	1		*REAR TAILGATE	Bent	1,506.10 F	*1,272.00 FL
18	1		*REAR TAILGATE WIPER MOTOR	Jammed	485.50 F	*485.50 FL
19	1		*REAR TAILGATE LOCK	Dented	255.90 F	*255.90 FL
20	1		*REAR TAILGATE LOCK COVER	Serviceable	29.30 F	*- FL
21	1		*REAR TAILGATE OUTER GARNISH	Mtg Cracked	320.20 F	*320.20 FL
22	1		*REAR TAILGATE INNER TRIMBOARD	Mtg Cracked	420.10 F	*420.10 FL
23	1		*REAR TAILGATE INNER HOLDER	Serviceable	62.10 F	*- FL
24	1		*REAR TAILGATE LOGO EMBLEM	Necessary	55.60 F	*55.60 FL
25	1		*REAR TAILGATE EMBLEM VALVEMATIC	Necessary	55.90 F	*55.90 FL
26	1		*REAR TAILGATE OUTER OPENING SWITCH	Serviceable	185.10 F	*- FL
27	1		*REAR TAILGATE REFLECTOR-H	Cracked	458.20 F	*312.20 FL
28	1		*REAR TAILGATE REFLECTOR-RH	Cracked	458.20 F	*312.20 FL
29	1		*REAR BUZZER SENSOR	Serviceable	189.00 F	*- FL
30	1		*REAR ELECTRONICS ANTENNA SENSOR	Cracked	198.00 F	*144.20 FL
31	1		*REAR FENDER INNER TRIMBOARD-LH	Mtg Cracked	658.50 F	*658.50 FL
32	1		*REAR FENDER INNER TRIMBOARD-RH	Mtg Cracked	658.50 F	*658.50 FL
33	1		*REAR WIPER BLADE	Serviceable	45.20 F	*- FL
34	1		*REAR EXHAUST MUFFLER	Repair	650.00 F	*- FL
35	1		*REAR FENDER-RH	Repair	1,150.90 F	*- FL
36	1		*REAR FENDER GLASS MOULDING-RH	Not Necessary	95.10 F	*- FL
37	1		*REAR END INNER PANEL	No such part	388.90 F	*- FL
38	1		*REAR FENDER WINDSCREEN SEALANT-RH	Not Necessary	60.00 F	*- FL
39	1		*REAR TAILLAMP PANEL-RH	Repair	189.20 F	*- FL
40	1		*REAR SPARE WHEEL PANEL	Repair	950.90 F	*- FL
41	1		*REAR CHASSIS MEMBER-RH	Repair	950.80 F	*- FL
42	1		*REAR TAILGATE ABSORBER-LH	Serviceable	220.50 F	*- FL
43	1		*REAR TAILGATE ABSORBER-RH	Serviceable	220.50 F	*- FL
44	1		*REAR WHEEL PANEL TOOL BOX	Serviceable	256.20 F	*- FL
45	1		*REAR WHEEL PANEL TRIMBOARD	Serviceable	310.00 F	*- FL
46	1		*REAR TAILGATE STOPPER RUBBER-LH	Serviceable	35.00 F	*- FL
47	1		*REAR TAILGATE STOPPER RUBBER-RH	Serviceable	35.00 F	*- FL
48	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
49	1		*SET REVERSE SENSORS	Dented	300.00 FS	*200.00 FS
50	1		*REVERSE CAMERA	Shorted	350.00 FS	*300.00 FS
51	1		*REAR NUMBER PLATE	Dented	60.00 FS	*45.00 FS
52	1		*REAR TAILGATE WEATHERSTRIP (50%)	Distorted/Dented	175.90 FS	*87.95 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Sub Total (\$)					16,521.35	8,385.30
- List Item Discount on L Items 0.00/25.00% (\$)					0.00	1,928.09
Total Parts (\$)					16,521.35	6,457.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,800.00	900.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,800.00	1,100.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	200.00	60.00
4	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	New	280.00	120.00
5	TO REMOVE/REFIT REAR PASSENGER SEAT,FENDER GARNISHES TO FACILITATE REPAIRS	New	250.00	120.00
6	TO REMOVE/TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
7	TO CHECK WIRING FUNCTIONS	New	80.00	20.00
8	COMPUTER DIAGNOSTIC RESET	New	250.00	0.00
9	WHEEL ALIGNMENT	New	120.00	0.00
10	TO REMOVE REAR FENDER GLASS & LABOUR	New	280.00	0.00
Gross Labour Cost (\$\$)			5,210.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >