474.4 +164.8 + 22 + 20	544.96 + 220 + 20 + 220
681.20 -20%	1004.96
544.96	

Not Normailed Russing Bapaing

Vehicle Insured: SHD 3379 Y

Accident Date : 29-Aug-2020

Date: 31-Aug-2020

No.: 31388

Our Ref: 020401 (FIRST) / QUEK

PAGE: 1

LEE SIEW MEI CORINA (MS)

Singapore

ESTIMATED COST OF REPAIR FOR HYUNDAI AD AVANTE 1.6GLS(A) (2019) SMK1558P

Less 20% :

Bullen 1 pc front bumper 474.40 1 pc o/s front bumper side retainer Sh 15.00 X 1 pc front bumper signallamp sen 164.80 -1 pc front bumper lower side grille sin 22.00 -1 pc front bumper lower side m 25.00 X garnish 1 pc front bumper lower spoiler @ S\$ 2.00 kg 71.70 K 10 pcs front bumper clips 1 pc o/s headlamp assy
1 pc o/s headlamp lower bracket 3,034.90 7× NN 25.00 ? X NN 3,852.80

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

300.00 224

3,082.24

To focus headlamps. To check front wiring and lighting operation.

30.00 201

To putty and respray on affected portions.

400.00 2201

Total:

-770.56

S\$ 3,812.24 =========

Singapore Dollars Three Thousand Eight Hundred and Twelve and Cents Twenty Four Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To displey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to finel approval from insurance Company

Acknowledged by Repairer Signature:

Date:

Scanned with CamScanner