

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010199/GES3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800025248
Claimant
Vehicle No : SKW913P **Insured Vehicle No :** SKJ3667Z
Date of Loss: 28/08/2020 Nature of Claim: TP Claim No: 9180318483SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW913P**
Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B4023168
Reg. Date: 16/10/2015 (Man. Year: 2015) Chassis No: RU11103166
Colour: White Odometer: 70412 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,017.84	796.40	221.44	21.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	400.00	400.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,817.84	1,196.40	621.44	34.19
+ GST 7.00/7.00% (S\$)	127.25	83.75	43.50	34.18
Nett Amount (S\$)	1,945.09	1,280.15	664.94	34.19
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		1,549.15		

INSPECTION

Date of Assignment: 23/09/2020
Date Inspected: 23/09/2020 Inspected At: Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A,
#01-15/16 & 17, AMK Autopoint
Singapore 568047
Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	963.00 FL	*762.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
3	1		*FRONT BUMPER CORNER RETAINER	Broken	25.30 FL	*25.30 FL
4	1		*FRONT FENDER PROTECTOR RH	Broken	206.00 FL	*140.20 FL
5	10		*FRONT FENDER PROTECTOR CLIPS	Necessary	40.00 FL	*30.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,272.30	995.50
- List Item Discount on L Items 20.00/20.00% (\$)	254.46	199.10
Total Parts (\$)	1,017.84	796.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF FRONT FENDER AND PARTS REPLACEMENT	New	350.00	200.00
2	TO RESPRAY AFFECTED AREAS	New	450.00	200.00
Gross Labour Cost (S\$)			800.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >