

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20010201/USD3E2

Date: 29/10/2020

REFERENCE

Insured/Claimant:	AMD SERVICES PTE LTD	Policy No:	DMCVSN3079781900
Date of Loss:	21/09/2020	Nature of Claim:	OD
		Claim No:	SNM20D203461/C01/CHUAKK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB4945M	Engine No:	1KD1924940
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y00K200562
Reg. Date:	20/05/2009 (Man. Year: 2009)	Odometer:	402250 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$18,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,380.00	1,655.00	725.00	30.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,159.59	1,008.39	151.20	13.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,539.59	2,663.39	876.20	24.75
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	3,539.59	2,163.39	1,376.20	38.88
+ GST 7.00/7.00% (S\$)	247.77	151.44	96.33	38.88
Nett Amount (S\$)	3,787.36	2,314.83	1,472.53	38.88

INSPECTION

Date of Assignment:	23/09/2020	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	23/09/2020	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Oct 2020)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB4945M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		2,260.00 F	*1,535.00 F
<u>Supplementary #1</u>						
2	1		*bumper cross member	Bent	100.00 F	*100.00 F
3	1		*bumper bracket	Bent	20.00 F	*20.00 F
					Total Parts (S\$)	2,380.00
						1,655.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOTAL LABOUR	New	1,159.59	1,008.39
Gross Labour Cost (S\$)			1,159.59	1,008.39

Report was unsubmitted during this print-out.

< END OF ESTIMATES >