

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CS/CT 200/0202/49f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SD 8322D

at Workshop m/s

2,00 60

of

Insured:

Policy No. DMHCSNA00004172001Claims No. SNM20D203481C02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$18500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 13 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SD 8322D

Yr Regn:

4, 28

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Toyota wish

C.C.

1794

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

723165

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

green max

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

1

mm

L/Bal.

6

mm

D.O.A.

22/9/20

D.O.I.

23/9/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

asky plk. 17AF10342We 3-4-2023 Sol 2yrs. bnd.Nett 81586/10/20 1/5 @ 8000 confirmed with ELF (Red \$52556.50, 87%)

06/10/20@4.24pm revised to Tan Kah Leong via Merimen.

Date/Time, File Pass to?

☐

: Preli. Report

1) 06/10 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 13Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS \$1☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

MER-TPLump Sum 11.11.11 (\$8000

TOTAL



Rico 60 Auto Services Pte Ltd, Blk 8, Kaki Bukit Avenue 4, #02-24
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SJD 8322 D
TOYOTA WISH

Noted
1/54 8000/
13 day
23/9/20

Submit to insurance.

Alk 1 mtd Rep 23/9/20

ATTN	NO.	DESCRIPTION - PARTS	QTY	PRICE
	1	BONNET <i>Buc ✓</i> 678.10	1	\$1386.00 ✓
	2	BONNET LOGO (TOYOTA) <i>neu ✓</i> 68.50	1	\$125.00 ✓
	3	BONNET INSULATOR <i>11X</i>	1	\$593.00 X
	4	BONNET HINGE (L+R) <i>11X</i>	2	\$310.00 X
	5	BONNET RUBBER STRIP <i>11X</i>	2	\$372.00 X
	6	BONNET STOPPER (L+R) <i>11X</i>	2	\$52.00 X
	7	HEADLAMP (L+R) <i>holder cr — 689.10 x 2 = 1378.20</i>	2	\$4064.00 ✓
	8	HEADLAMP BRACKET (L+R) <i>NA X</i>	2	\$540.00 X
	9	HEADLAMP PANEL (L+R) <i>buflaw 12X</i>	2	\$722.00 X
	10	FRONT GRILLE <i>cr — 166.60</i>	1	\$749.00 ✓
	11	FRONT BUMPER <i>Dis — 645.10</i>	1	\$1211.00 ✓
	12	FRONT BUMPER RETAINER (L+R) <i>Bu — 65.50 x 2 = 131.00</i>	2	\$310.00 ✓
	13	FRONT BUMPER GRILLE <i>To. — 148.20</i>	1	\$595.00 ✓
	14	FRONT BUMPER BRACKET (L+R) <i>NS X</i>	2	\$480.00 X
	15	FRONT BUMPER REINFORCEMENT BAR <i>Bu — 295.30</i>	1	\$873.00 ✓
	16	FRONT BUMPER SPONGE <i>12X</i>	1	\$379.00 X
	17	FRONT BUMPER FOG LAMP (L+R) <i>350 11 * 1/5 cr 1 pc 350 \$415.00</i>	2	\$830.00 1 pc
	18	FRONT BUMPER FOG LAMP GARNISH (L+R) <i>11X</i>	2	\$594.00 X
	19	FRONT BUMPER FOG LAMP CHROME (L+R) <i>11X</i>	2	\$632.00 X
	20	FRONT FENDER (L+R) <i>12 X</i>	2	\$1572.00 X
	21	FRONT FENDER QUARTER GLASS MOULDING (L+R) <i>11X</i>	2	\$622.00 X
	22	FRONT FENDER SIGNAL LAMP (L+R) <i>11X</i>	2	\$558.00 X
	23	FRONT FENDER COWLING (L+R) <i>21/70 cr — 188.20 x 2 = 376.40</i>	2	\$576.00 ✓
	24	FRONT FENDER TOP GARNISH (L+R) <i>11X</i>	2	\$252.00 X
	25	FRONT SUPPORT PANEL <i>Buflaw — 688.10</i>	1	\$1013.00 ✓
	26	FRONT SUPPORT PANEL TOP GARNISH <i>Bu — 248.50</i>	1	\$497.00 ✓
	27	AIRCON CONDENSOR <i>Bent / pu — 1213.00</i>	1	\$1253.00 ✓
	28	HIGH PRESSURE HOSE <i>11X</i>	1	\$497.00 X
	29	LOW PRESSURE HOSE <i>11X</i>	1	\$511.00 X
	30	RADIATOR <i>SUC X</i>	1	\$1497.00 X
	31	RADIATOR SPARE TANK <i>11X</i>	1	\$250.00 X
	32	SUCTION PIPE <i>11X</i>	1	\$403.00 X
	33	DISCHARGE PIPE <i>11X</i>	1	\$450.00 X
	34	RADIATOR FAN COWLING <i>SUC X</i>	1	\$812.00 X
	35	RADIATOR FAN BLADE <i>11X</i>	1	\$176.00 X
	36	RADIATOR FAN MOTOR <i>11X</i>	1	\$957.00 X
	37	WIPER WASH TANK <i>11X</i>	1	\$240.00 X
	38	WIPER WASH MOTOR <i>11X</i>	1	\$397.00 X
	39	REAR WINDSCREEN MOULDING <i>neu ✓</i> 128.70	1	\$391.00 ✓
	40	TAILGATE <i>Bu 1248.10</i>	1	\$1563.00 ✓

[illegible]

4	FRONT CARPLATE FRAME	X	1	\$	120.00	X
5	FRONT FENDER COWLING CLIPS	11 X	10	\$	100.00	X
6	FRONT FENDER QUARTER WINDOW SEALANT	11 X	1	\$	120.00	X
7	RADIATOR COOLANT	11 X	1	\$	100.00	X
8	REAR WINDSCREEN SEALANT	11 40	1	\$	120.00	40
9	TAILGATE INNER BOARD CLIPS	11 50	10	\$	100.00	50
10	TAIL LAMP CLIPS	11 X	4	\$	80.00	X
11	REAR CARPLATE	11 X	1	\$	120.00	X
12	REAR CARPLATE FRAME	11 X	1	\$	120.00	X
13	REAR BUMPER CLIPS	11 50	10	\$	100.00	50
14	REAR FENDER SEALANT	11 X	1	\$	120.00	X
15	REAR FENDER QUARTER WINDOW SEALANT	11 X	1	\$	120.00	X
16	REAR FENDER INNER TRIM CLIPS	11 X	10	\$	100.00	X
17	REAR FENDER COWLING CLIPS	11 X 11 40	10	\$	100.00	X
18	REAR QUARTER PANEL SEALANT	11 X	1	\$	120.00	X
19	END PANEL SEALANT	11 50	1	\$	120.00	50
20	SPAREWHEEL PANEL SEALANT	11 X	1	\$	120.00	X
21	REAR Bumper Reverse Sensor Set (Refer to parts no. 64)	\$250.00			450	
SPECIAL NETT TOTAL				\$	1,440.00	
LABOUR			QTY	PRICE		
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	2000	1	\$	6,300.00	
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1800	1	\$	4,200.00	
3	TO RUST PROOF ACCIDENT AFFECTED AREA	150	1	\$	600.00	
4	TO RNR REAR WINDSCREEN	120	1	\$	400.00	
5	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	100	1	\$	300.00	
6	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS		1	\$	150.00	
7	TO CHECK WIRING LAYOUT AND FOG LAMP FUNCTION	30	1	\$	150.00	
5	TO RNR REAR FENDER QUARTER WINDOW	11 X	1	\$	400.00	
6	TO RNR UPHOSTERY, GARNISH AND ATTACHMENT PARTS	80	1	\$	1,200.00	
7	TO RNR REVERSE SENSOR & CHECK FUNCTION.	50	1	\$	150.00	
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	60	1	\$	450.00	
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	Repaid X	1	\$	150.00	
10	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	11 X	1	\$	350.00	
10	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.	11 X	1	\$	800.00	
11	TO DO WATER LEAK TEST.	11 X	1	\$	120.00	
L: \$4390 4390				TOTAL	\$	15,720.00
				GRAND TOTAL COST	\$	17,160.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-8118.37

S.N-450

L-4390

12998.37