Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20010206/AVD3Q2

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

08/03/2021 Date: Singapore 079120

REFERENCE

NG CHOON SENG Policy No: 2070107981 Insured/Claimant:

Date of Loss: 20/09/2020 Nature of Claim: OD Claim No: 3708286559SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDH9199L**

Make & Model: AUDI A4, 2.0 TFSI QU S-TRONIC (A) Engine No: DFM023874

Reg. Date: 24/07/2020 (Man. Year: 2020) Chassis No: WAUZZZF43LA062306

Colour: Black Odometer: 2964 km

Engine Capacity: 1984 cc

Market Value/New Car

S\$145,000.00 Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18 Rear Left Side: Front Left Side: Goodyear 6 mm Goodyear 6 mm Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,643.00	3,470.80	2,172.20	38.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,322.00	1,522.00	800.00	34.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,965.00	4,992.80	2,972.20	37.32
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	7,415.00	4,442.80	2,972.20	40.08
+ GST 7.00/7.00% (S\$)	519.05	311.00	208.05	40.08
Nett Amount (S\$)	7,934.05	4,753.80	3,180.25	40.08

INSPECTION

Date of Assignment: 23/09/2020

Premium Automobiles Pte Ltd (UBI) Date Inspected: 23/09/2020 Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,122.00 FS	*1,697.60 FS
2	1		*FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE	Cracked	259.00 FS	*206.80 FS
3	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	187.00 FS	*149.60 FS
4	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*-FS
5	1		*FRONT BUMPER SUPPORT-LH	Not Necessary	28.00 FS	*-FS
6	1		*LOCK CARRIER BRACKET	Not Necessary	136.00 FS	*-FS
7	1		*RADIATOR GRILLE	Cracked	1,562.00 FS	*1,249.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Cut	134.00 FS	*107.20 FS
9	1		*RADIATOR AIR GUIDE-LH OUTER	Not Necessary	16.00 FS	*-FS
10	1		*RADIATOR AIR GUIDE-LH INNER	Not Necessary	44.00 FS	*-FS
11	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
12	1		*SUNDRIES	Not Necessary	300.00 FS	*-FS
F=Fra	inchise	part. S=S	pcNett.	Total Parts (S\$)	5,643.00	3,470.80
			Report was unsubmitted during this	s print-out.		

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	280.00	280.00					
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RADIATOR GRILLE.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	New	1,050.00	500.00					
3	TO RESPRAY FRONT BUMPER.	New	800.00	550.00					
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00					
	Gross Labour Cost (S\$)		2,322.00	1,522.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >