

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010207/AVF3E2

Date: 02/03/2021

REFERENCE

Insured/Claimant: TEY SU MIN, JUNE(ZHENG SHUMIN, JUNE) Policy No: 2100301745-08
Date of Loss: 18/09/2020 Nature of Claim: OD Claim No: 7325633211SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB1508E**
Make & Model: AUDI A1, 1.4 1.4TFSI (A) Engine No: CAXA93994
Reg. Date: 31/05/2012 (Man. Year: 2012) Chassis No: WAUZZZ8X4CB226485
Colour: White Odometer: 136047 km
Engine Capacity: 1390 cc
Market Value/New Car Price: S\$28,500.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R16 Rear Tyre Size: 215/45R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,584.00	3,325.00	13,259.00	79.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,632.00	4,192.00	6,440.00	60.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,216.00	7,517.00	19,699.00	72.38
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	25,216.00	5,517.00	19,699.00	78.12
+ GST 7.00/7.00% (S\$)	1,765.12	386.19	1,378.93	78.12
Nett Amount (S\$)	26,981.12	5,903.19	21,077.93	78.12

INSPECTION

Date of Assignment: 23/09/2020
Date Inspected: 23/09/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Please be informed that OI had decided to withdraw his own policy claim.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$6,120.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,530.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	165.00 FS	*- FS
4	1		*FRONT SPOILER	Not Necessary	188.00 FS	*- FS
5	1		*FRONT BUMPER FOAN FILLER PIECE	*Check	116.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cracked	959.00 FS	*959.00 FS
7	1		*FRONT REINFORCEMENT BEAM	*Check	684.00 FS	*- FS
8	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*14.00 FS
9	1		*AICON STICKER	Necessary	37.00 FS	*37.00 FS
10	1		*BONNET	Dented	2,235.00 FS	*2,235.00 FS
11	1		*BONNET ATTACHMENT PARTS	Not Necessary	137.00 FS	*- FS
12	2		*BONNET LID HINGE-LH/RH	*Check	252.00 FS	*- FS
13	2		*BONNET COVER-LH/RH	Not Necessary	64.00 FS	*- FS
14	1		*BONNET EDGE PROTECTION-FRONT	Necessary	20.00 FS	*20.00 FS
15	1		*BONNET CATCH HOOK	Not Necessary	65.00 FS	*- FS
16	2		*BONNET LOCK BAR	Not Necessary	98.00 FS	*- FS
17	1		*BONNET CATCH HOOK	Not Necessary	63.00 FS	*- FS
18	2		*BONNET LID LOCK	Not Necessary	423.00 FS	*- FS
19	1		*BONNET BOWDEN CABLE-CENTRE	Not Necessary	57.00 FS	*- FS
20	2		*FRONT DOOR-LH/RH	Repair	4,018.00 FS	*- FS
21	1		*DOOR ATTACHMENT PARTS	Not Necessary	132.00 FS	*- FS
22	2		*DOOR CATCH	Not Necessary	176.00 FS	*- FS
23	1		*TYRE PRESSURE DATA PLATE	Not Necessary	37.00 FS	*- FS
24	2		*WINDOW APERTURE SEAL-LH/RH OUTER	Not Necessary	268.00 FS	*- FS
25	2		*CROSS MEMBER REINFORCEMENT	Not Necessary	32.00 FS	*- FS
26	2		*HEADLIGHT MOUNTING-LH/RH	*Check	206.00 FS	*- FS
27	2		*HEADLIGHT-LH/RH	*Check	3,862.00 FS	*- FS
28	1		*LIFT CYLINER-LH	Not Necessary	141.00 FS	*- FS
29	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
30	1		*SUNDRIES	*Check	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 16,584.00 3,325.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES (*Check)	New	700.00	0.00
3	TO REMOVE AND TRANSFER BOTH FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	560.00	250.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET,BOTH FRONT DOORS,BOTH HEADLIGHTS,TO REPAIR BOTH FRONT FENDERS.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,900.00	1,000.00
5	TO RESPRAY FRONT BUMPER,BONNET,BOTH FRONT BOTH FRONT FENDERS AND BOTH FRONT DOORS	New	4,000.00	2,750.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			10,632.00	4,192.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >